

تقرير الفحص – 2010 كوماتسو D375A-5

الرقم التسلسلي: KMT00050J02019472 | ساعات: ٤٤٦٤٨ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٧٣

Key Features & Condition

N/A	Safety Certification Label
Yes	Ground Ripper
Yes	Ripper Control Valve
N/A	Low Ground Pressure Tracks
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Grade Control System
N/A	Equipment Parts Manual
N/A	CAT System One
Yes	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok	Washer, Wipers
Not functional	Air Conditioning & Heating System
Ok, minor cut	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
SA6D170E-3	Engine Model
Ok	Engine Cooling System



Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Normal water	Coolant
Ok, minor leak from first head cover gasket	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Push Frame & Trunnions
Ok	Doors, Covers, and Grilles
Ok	Access Steps & Handrails
Ok	Exterior Paint Condition
Ok	Blade Trunnions & Bushings
Ok	Underbody Protection Plates
Ok	Final Drive Condition
Ok	Fuel Tank, Roof, & Hood Condition
Ok	Lights and Battery Check
Ok	Push Arm Pivot Shaft
Ok	Tilt Linkage Pins & Bushings

Hydraulic System

Minor	Hydraulic Leaks
Ok	Ripper Lift Hydraulic Jacks
Ok	Ripper Angle Hydraulic Jacks
N/A	Tilt Hydraulic Jack
Ok	Angle Hydraulic Jack
Ok	Lift Hydraulic Jacks

Limited Functional Testing & Operation

Ok	Push Frame Pins
Ok	Blade Pins
Ok	Ripper Pins
Ok	Equalizer Bar Condition



Ok	Bulldozer Stall Test
Ok	Steering Function Test
Ok	Blade Tilt and Lift Test
Ok	Undercarriage Pivot Pins
Ok	Transmission Test
Ok	Brake System Test
Ok	Torque Converter Test

Blade Inspection

Ok	Blade Base Condition
Ok	Spill Rack Condition
Ok	Blade Front Condition
Ok	Blade Edge Condition

Undercarriage Inspection

-	Right Side Undercarriage Wear
20%	Undercarriage Bushings
60%	Undercarriage Shoes
50%	Front Idler Condition
N/A	Rear Idler Condition
50%	Carrier Roller Condition
50%	Track Links Condition
30%	Sprocket Condition
20%	Roller Condition
Ok	Track Canon Condition
-	Left Side Undercarriage Wear
20%	Undercarriage Bushings
60%	Undercarriage Shoes
50%	Front Idler Condition
N/A	Rear Idler Condition
50%	Carrier Roller Condition
50%	Track Links Condition
60%	Sprocket Condition
10%	Roller Condition



المعدات والآليات | تقويم المزادات

Ok
W610, H320 mm

Track Canon Condition
Track Width Measurement

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

