

تقرير الفحص – 2015 كاتربيلر 966H

الرقم التسلسلي: CAT0966HEBJ601213 | ساعات: ٣٣٥٥٢ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ٩١٧

Key Features & Condition

| | |
|-----|--------------------------------------|
| N/A | Safety Certification Label |
| N/A | Automatic Lubrication System |
| N/A | Auxiliary Hydraulic Valve |
| N/A | Equipment Parts Manual |
| Yes | Air Conditioning System |
| N/A | (Hydrostatic Drive System (Hydrostat |
| Yes | Supplemental Steering System |
| N/A | Operator's Manual |
| N/A | Emission Compliance Label |
| N/A | Quick Attachment Coupler |
| N/A | Load Weighing System |
| N/A | Horn Function |

Operator Cabin Details

| | |
|----------------------------------|-----------------------------------|
| Ok | Seat and Arm Support |
| Ok, cover is missing | Cab Doors & covers |
| Ok | Controls, Levers |
| Ok | Windows and Mirrors |
| Screen low visibility (sunburnt) | Dashboard Screen, Gauges |
| Screen low visibility (sunburnt) | Warning alarms message |
| Ok | Washer, Wipers |
| Ok, weak cooling | Air Conditioning & Heating System |
| Ok, minor cut | Cab Floor Covering |
| Ok | Cab Structure, Gard |
| Need minor service | Electrical System |

Engine & Performance

| | |
|------------|---------------------|
| Electronic | Fuel Injection Type |
|------------|---------------------|



| | |
|------------------|--------------------------|
| Cat C11 | Engine Model |
| Ok | Engine Cooling System |
| Ok, need change | Engine Oil Check |
| Normal | Blowby |
| Ok | Exhaust System & Muffler |
| Ok | Belts & Air/Oil Filters |
| Normal | Smoke |
| Ok, normal water | Coolant |
| Ok | Fluid Leaks |

Exterior Condition & Visual Inspection

| | |
|--------------------------------|----------------------------|
| Ok | Main Frame and Lift Arm |
| Ok, no lift hyd jack and motor | Engine Hood |
| Ok | Access Steps and Handrails |
| Ok | Exterior Paint Condition |
| Ok, minor welding | Counterweight Condition |
| Ok | Wheel Fenders |
| Ok, need 4 bulbs | Lights Check |
| Ok | Battery Check |

Power Train Inspection

| | |
|-----------|---------------------------|
| Ok | Axles and Differentials |
| Ok | Transmission Gearbox |
| Ok | Power Train force |
| Ok | Transmission Noise Check |
| Ok | Universal Joint Condition |
| Semi-auto | Transfer Gear Type |

Hydraulic System

| | |
|--|------------------------------|
| Ok | Hydraulic Leaks |
| Ok, tilt jack minor oil leak, and welded | Lift and Tilt Hydraulic Jack |
| Ok | Steering Hydraulic Orbital |
| Ok | Steering Hydraulic Jacks |
| Ok | Hydraulic Pumps and Valves |



Limited Functional Testing & Operation

| | |
|----------------------------|-----------------------------|
| Ok | Steering Function Test |
| Ok,4th gear not functional | Transmission Operation Test |
| Ok | Loader Stall Test |
| Ok | Brake System Test |
| Ok | Articulation Movement Check |
| Ok | Loader Attachment Pins |
| Ok | Electrical System Check |
| Ok | Supplemental Steering Test |

Attachments

| | |
|----------------------|-------------------------------|
| W3100,H1400, D950 mm | Bucket Width and Capacity |
| Ok | Bucket Bottom Condition |
| Ok | Bucket Edge & Teeth Condition |
| Ok | Bucket Side Condition |
| Ok | Attachment Coupler |

Tires Inspection

| | |
|------------------|--------------------------------|
| - | Front Right |
| TRIANGLE 26.5R25 | Tire Brand & Size Details |
| 40% | Tire Remaining Life Percentage |
| Ok | Tire Condition Notes |
| Ok | Wheel Rims & Nuts |
| - | Front Left |
| TRIANGLE 26.5R25 | Tire Brand & Size Details |
| 40% | Tire Remaining Life Percentage |
| Ok | Tire Condition Notes |
| Ok | Wheel Rims & Nuts |
| - | Rear Right |
| TRIANGLE 26.5R25 | Tire Brand & Size Details |
| 40% | Tire Remaining Life Percentage |
| Ok | Tire Condition Notes |
| Ok | Wheel Rims & Nuts |



| | |
|------------------|--------------------------------|
| - | Rear Left |
| TRIANGLE 26.5R25 | Tire Brand & Size Details |
| 40% | Tire Remaining Life Percentage |
| Ok | Tire Condition Notes |
| Ok | Wheel Rims & Nuts |

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

