

## تقرير الفحص – 2017 هيونداي Robex 500LC-7

الرقم التسلسلي: HHKHNB02PE0000907 | ساعات: ٦٥٠١ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٦٩

### Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn

### Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, right mirror missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
E381, E141, E45, E33, E25	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
-	Electrical System

### Engine & Performance

Electronic	Fuel Injection System
CUMMINS QSM11-C Engine	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Normal water	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

## Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok, side catwalk missing	Bumpers & Catwalk Condition
Ok, minor welding on bucket pin bushing	Arm Condition
Not functional	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok, repainted	Exterior Paint Condition

## Hydraulic System

Minor leaks from fittings	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

## Performance analysis

Ok	Boom Pins Condition
Ok	Excavator self- Drift Test



Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, need side spacer	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

## Attachments

Bucket	Attachments model
W1580, H1500, D1150	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

## Undercarriage

60%	bushings
50%	Track shoes
40%	idlers
600	:shoe width in mm
80	:track pitch in mm
60%	carrier rollers
60%	Track rollers
50%	Track links
70%, left minor oil leak	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

