

تقرير الفحص – 2018 هيتاشي ZX470H

الرقم التسلسلي: THEJAHL0H00000298 | ساعات: ١٠٨٠١ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٧٠

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, mirrors missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Check engine	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Need minor service	Electrical System

Engine & Performance

Mechanical	Fuel Injection System
Isuzu AH-6WG1XYSA-01	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok, 1 light not functional	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok, boom jack pin minor loose	Boom Pins Condition
Ok	Excavator self- Drift Test



Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, need side spacer	Bucket Pins Condition
Ok, swing gear little loose	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

Attachments

Bucket	Attachments model
W1700, H1500, D1200	Size
Ok, 1 tooth missing	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

70%	bushings
70%	Track shoes
L50%, R80%	idlers
600	:shoe width in mm
80	:track pitch in mm
70%	carrier rollers
60%	Track rollers
60%	Track links
60%	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

