

تقرير الفحص – 2012 دوسان DX340LC

ساعات: ١١٤٧٠.٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٣٢٠٥٥٢

Key Features & Condition

| | |
|-----|-------------------------------------|
| N/A | Safety Certification Label |
| N/A | Boom Hydraulic Check Valve |
| N/A | Adjustable Boom System |
| N/A | Automatic Lubrication System |
| N/A | Arm Hydraulic Check Valve |
| N/A | Diesel Particulate Filter |
| N/A | Hydraulic Hammer Lines |
| N/A | Grapple And Shear Hydraulic Lines |
| N/A | Diesel Exhaust Fluid System Addblue |
| N/A | Stabilizer Blade Condition |
| N/A | Horn |

Operator Cabin Details

| | |
|---|-----------------------------------|
| Ok | Seat And Arm Support |
| Ok, door lock need repair | Cab Doors & Covers |
| Ok, right control stick is broken | Control Levers, Control Stick |
| Ok, no mirrors | Windows And Mirrors |
| Functional, monitor controls not functional and monitor base is missing | Dashboard Screen, Gauges |
| Ok | Warning Alarms Message |
| N/A | Washer, Wipers |
| Not functional | Air Conditioning & Heating System |
| Ok | Cab Floor Covering |
| Ok | Cab Structure, Gard |
| Ok | Electrical System |
| Diesel tank cover is missing | Note |

Engine & Performance

| | |
|------------|-----------------------|
| Electronic | Fuel Injection System |
|------------|-----------------------|



| | |
|--------------|--------------------------|
| Doosan DL08 | Engine Model |
| Ok | Engine Cooling System |
| Ok | Engine Oil Check |
| Ok | Cooling System |
| Normal water | Coolant |
| Ok | Exhaust System & Muffler |
| Ok | Belts & Air/Oil Filters |
| Normal | Smoke Check |
| Normal | Blowby |
| Ok | Leaks & Seals |

Exterior Condition & Visual Inspection

| | |
|--------------------------------|-----------------------------|
| Ok | Main Frame & Track Frame |
| Ok | Protective Covers & Sheets |
| Ok | Engine Hood |
| .Ok, the battery box is dented | Side Access Doors |
| Ok | Steps And Handrails |
| Ok | Boom Condition |
| Ok | Bumpers & Catwalk Condition |
| Ok | Arm Condition |
| Ok, 1 light need change | Lights |
| Need change | Battery Check |
| Ok | Cabin Compartments |
| Ok, some parts repainted | Exterior Paint Condition |

Hydraulic System

| | |
|----|------------------------------|
| Ok | Hydraulic Leaks |
| Ok | Boom Hydraulic Jack |
| Ok | Hydraulic Pump & Valve Block |
| Ok | Bucket Hydraulic Jack |
| Ok | Arm Hydraulic Jack |

Performance analysis

| | |
|----|---------------------|
| Ok | Boom Pins Condition |
|----|---------------------|



| | |
|-----------------|-------------------------------------|
| Ok | Excavator Self- Drift Test |
| Ok | Arm Pins Condition |
| Ok | Hydraulic Pump Noise Check |
| Ok, minor loose | Bucket Pins Condition |
| Ok | Slewing Ring Bearing Movement Check |
| Ok | Swing Drive And Brake Test |
| Ok | Drive Force Test |

Attachments

| | |
|-------------------------|--------------------------|
| bucket | Attachments Model |
| W1080, H1200, D1000 mm | Size |
| Ok, 4 teeth are missing | Status |
| Ok | Coupler Status |
| N/A | Second Attachments Model |
| N/A | Size |
| N/A | Status |

Undercarriage

| | |
|-----|--------------------|
| 60% | Bushings |
| 50% | Track Shoes |
| 60% | Idlers |
| 600 | :Shoe Width In Mm |
| 85 | :Track Pitch In Mm |
| 30% | Carrier Rollers |
| 40% | Track Rollers |
| 60% | Track Links |
| 70% | Sprocket Segments |

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

