

تقرير الفحص – 2021 كاتربيلر 320

ساعات: ٢٨٣٩.٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٣٩٦٠٦٩

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn
Yes	Rear Camera
Yes	Machine Angle Sensor

Operator Cabin Details

Ok	Seat and Arm Support
Ok, need lock repair	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, front window is cracked, right window need silicon seal, right mirror is missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Error 4576-11, Error 4576-4	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok, no guard	Cab Structure, Guard
Ok, need minor service(check errors)	Electrical System

Engine & Performance



Electronic	Fuel Injection System
C7.1	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Ok, normal water	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok, 2 doors lock need repair	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok	Boom Pins Condition
----	---------------------



Ok	Excavator self- Drift Test
Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

Attachments

Bucket (1.19 m³)	Attachments model
W1070,H1190,D880 mm	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

70%	bushings
70%	Track shoes
70%	idlers
600	:shoe width in mm
75	:track pitch in mm
70%	carrier rollers
70%	Track rollers
70%, 1 link need repair	Track links
70%	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

