

## Inspection report – 2015 Tadano GR-600EX

Serial No: 549126 | Hours: 27731 | Location: Dubai, United Arab Emirates | SKU: 950

---

### Key Features & Condition

CE Labeling	N/A
Automatic Shift	Yes
Semi-Automatic	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Extended Fuel tank	N/A
Retarder	Yes
2 Axle Steering	Yes

---

### Truck Cab

Driver Seat	Ok, need seat cover
Switches, Levers	Ok
Gauges, Warn Lights	Screen need service (sunburnt)
Aircon / Heater	N/A
Cab Doors	Ok
Windows, Mirrors	Ok
Wipers, Washers	Ok
Interior, Covers	Ok

---

### Engine

Injection Type	Mechanical
Engine Model	mitsubishi 8m80-tl
Leaks, Seals	Ok
Oil Condition	Ok
Exhaust/Muffler	Ok
Cooling System	Ok
Smoke, Fume	Normal
Blow By	Normal

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Belts, Pulleys	Ok
Coolant Condition	Ok

---

## Visual inspection exterior

Chassis, Frames	Ok
Sheet Metal, Covers	Ok, minor rust
Steps, Grab Irons	Ok
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok
Lights	Not functional
Batteries	Need replace
Main Hook	Ok
Auxiliary Hook	N/A

---

## Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Automatic
Clutch	N/A

---

## Hydraulics / Steering

Hoses & Lines	Ok
Hydraulic Pump	Ok
PTO	Ok
Steering Cylinders	Ok
Steering Linkage	Ok
Lift Limitations	Ok
Outriggers	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Crane Condition / Limited Test

Drive Forward & Back	Ok
Controls, Levers	Ok
Boom Conditions	Ok
Telescopic Segments	Ok
Hydraulic Cylinders	Ok
Swing Bearing / Drive	Ok
Hose Lines	Ok
Lift Limitations	Ok
Main Hook	Ok
Auxiliary Hook	N/A
Outriggers	Ok

---

## Tires Condition %

Right	-
Axle 1	60%
Axle 2	60%
Left	-
Axle 1	60%
Axle 2	80%
Size / Brand	29.5-25 Bridgestone

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

