

PLANT & EQUIPMENT

Rapport d'inspection – 2011 Tata 1618

Numéro de série: MAT449373B2L00513 | Km: 405470 | Lieu: Dubai, Émirats arabes unis | SKU: 655

Key Features & Condition

Towing Attachment	N/A
Recovery	N/A
Xenon Headlights	N/A
Seat Belt	Yes
Closed Deck Box	N/A
Air Conditioning System	N/A
With Crane	Yes
Dump Truck Deck	N/A
Spare Tire	Yes
Fire Extinguisher	Yes

Cab Interior Inspection

Seat Condition	Need upholstery
Control Switches	Functional
Dashboard Gauges	Ok, rpm not functional
Air conditioner	Not functional
Cab Ceiling Condition	Ok
Warning Lights	N/A
Cabin Lifting Jack	Need upper pin assembly
Cab Doors	Ok, right door rust damaged, outside lock need repair
Window Condition	Ok
Windshield Wipers	Ok
Cab Floor Covering	Ok, not original
Radio	N/A
Spare Tire Condition	N/A
Structure	minor rust damage on bottom

Engine Inspection

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Fuel Injection Type	Mechanical
Fluid Leaks	Minor oil leak
Engine Oil Check	Ok
Exhaust System	Ok
Engine Cooling System	Ok
Coolant	Ok, normal water
Engine Serial Number	N/A
Engine Noise Check	Normal
Engine Blow-by Check	Normal
Engine Belts	Ok
Engine Power Output	Ok

Exterior Inspection

Main Frame Structure	Ok, little rusty
Body Metal	Ok
Door Handle Condition	Ok
Exterior Paint Condition	Need repaint
Radiator Grill Condition	Ok
Bumper Condition	Ok, minor dent
Light Condition	Ok, left is broken
Battery Condition	Ok

Hydraulic system

Hydraulic Hoses, Lines, & Swivel Joints	Ok
Hydraulic Pump & Valve Block	Ok
Hydraulic Controls & Levers	Ok
Crane Hook Condition	Ok
Leaks	Minor oil leak from tank breather valve, crane swing drive
Boom Hydraulic Cylinders	Ok
Stick Hydraulic Cylinder	Ok
Telescopic Boom Segments	Minor oil leak
Outrigger Condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Power Train Inspection

Axles Condition	Ok
Transmission Gearbox	Functional
Transmission Gear	Functional
Transfer Gear System	Functional
Universal Joint Condition	Functional
Differential Condition	Functional
Brake Drum/Disk Condition	Functional
Clutch Condition	Functional

Operational Test

Forward Drive Test	Functional
Reverse Drive Test	Functional
Service Brake Test	Functional
Steering Function Test	Functional
Wheel Bearing Check	Ok
Suspension Check	Functional
Parking Brake Test	Ok
Crane Function Test	Functional

Crane Specifications pal finger pk10000

Lifting moment (mt)	9.5
Outreach (m)	6.2
Slewing angle (°)	400
Slewing torque (mt)	1.20
Pressure (MPa)	31.5
Pump capacity (l/min)	30 - 45
Crane Weight (kg)	1031
Crane Height (mm)	2016
Crane Width (mm)	2415
Installation Width (mm)	657

Tire Inspection

Front Side Axle	-
-----------------	---

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Condition %	70%
Tire Cuts and Damage	Ok
Recapped Tires	No
Rear Side Axle	-
Condition %	50%
Tire Cuts and Damage	Ok
Recapped Tires	No

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

