

تقرير الفحص – 2004 كاتربيلر M318

الرقم التسلسلي: 8AL02321 | ساعات: ٢٨١٢٣ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٧٩٦

Key Features & Condition

N/A	Safety Certification Label
Yes	Boom Hydraulic Check Valve
Yes	Adjustable Boom System
N/A	Automatic Lubrication System
Yes	Arm Hydraulic Check Valve
N/A	Back camera
N/A	Quick Coupler
Yes	Hydraulic Hammer Lines
Yes	Grapple and Shear Hydraulic Lines
N/A	Stabilizer Blade Condition
N/A	Horn
Yes	Schild Plate

Operator Cabin Details

Ok	Seat and Arm Support
Ok, no cover and lock need repair	Cab Doors & covers
Functional	Control Levers, Control Stick
Ok, right mirror is missing	Windows and Mirrors
N/A	Dashboard Screen, Gauges
N/A	Warning alarms message
N/A	Washer, Wipers
N/A	Air Conditioning & Heating System
N/A	Cab Floor Covering
Ok, no guard	Cab Structure, Gard
Need repair	Electrical System

Engine & Performance

Mechanical	Fuel Injection Type
3116T	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Minor	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok, normal water	Coolant
Minor leaks	Leaks& seals
Need repair	Battery Alternator

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
N/A	Lights
N/A	Battery Check
Ok	Counterweight
Ok	Exterior Paint Condition

Hydraulic System

Minor	Hydraulic Leaks
Functional	Boom Hydraulic Jack
Functional	Hydraulic Pump & Valve Block
Functional	Mono Boom Jack
Functional	Bucket Hydraulic Jack
Functional	Arm Hydraulic Jack
Normal	Pump Noises Check
N/A	Bucket Swing cylinder



Transmission & drive train

Functional	Transmission Gear
Ok	Axles
Ok	Swivel Joint
Ok	Universal Joint

Limited Functional Testing & Operation

Ok, minor loose	Boom Pins Condition
Functional , weak	Excavator self- Drift Test
Ok	Arm Pins Condition
Normal	Hydraulic Pump Noise Check
Functional	Brack & Parking Brack
Ok	Suspension Lock
Ok	Bucket Pins Condition
Functional	Slewing Ring Bearing Movement Check
Functional	Swing Drive and Brake Test
Functional	Drive force Test
Ok	Slewing Ring Lock

Attachments

Bucket	Attachments model
W640, H1100, D800 mm	Size
Ok	Status
Ok	Coupler status
Schild blade	Second Attachments model
W2500, H550 mm	Size
Ok	Status

% Tires Estimated Remaining Life

30%	Front Right
20%	Front Left
25%	Rear Right
20%	Rear Left
10.00R20	Size



المعدات والآليات | تقويم المزادات

(Tube (on road
N/A
Minor
missing 1

Type
Spacer Rings
Damages / Cuts
Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

