

## تقرير الفحص – 2007 بوبكات S130

الرقم التسلسلي: A8KA11036 | ساعات: ٥٣١١ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٨١

### Key Features & Condition

N/A	Safety Certification Label
N/A	Operator's Manual
N/A	Equipment Parts Manual
N/A	Air Conditioning System
N/A	Emission Compliance Label
N/A	Closed Cabin
N/A	Horn Function

### Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
N/A, only rear window	Windows and Mirrors
Ok	Gauges
ACS warning, Air flow	Warning alarms message
N/A	Washer, Wipers
N/A	Air Conditioning & Heating System
N/A	Cab Floor Covering
Ok	Cab Structure, Guard
Need service	Electrical System
Broken	Start key
Not functional (bypass)	Main Safty Switch

### Engine & Performance

Mechanical	Fuel Injection Type
Kubota V2203-M-DI	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Minor	Blowby



Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Minor leak from fuel pump	Leaks & seals
Need minor service	Fuel System
Fuel pump solenoid valve needs changing (hard start, sudden off )	: Note

## Exterior Condition & Visual Inspection

Ok, minor welding, minor crack	Main Frame and Lift Arm
Ok	Protective Covers & Sheets
Ok	Engine Door
Not functional	Lights
Ok	Battery Check
Ok, fully repainted	Exterior Paint Condition

## Hydraulic System

Ok	Hydraulic Leaks
Ok	Lift and Tilt Hydraulic Jack
Ok	(Steering Hydraulic Orbital (drive motor
Ok	Hydraulic Pumps and Valves

## Limited Functional Testing & Operation

Functional	Drive Function Test
Functional	Skid steer Stall Test
Functional	Brake System Test
Functional	Attachment Pins
Functional	Final Drive Motors Test
Not functional	Park Break

## Attachments

Bucket	Attachments model
W1530, H310, D500 mm	Size



# المعدات والآليات | تقويم المزادات

Ok	Bottom condition
Ok, no teeth	Edge & teeth condition
Ok	Bucket side condition
Ok	Coupler status

## % Tires Estimated Remaining Life

100%	Front Right
100%	Front Left
100%	Rear Right
100%	Rear Left
10-16.5	Size
Tube less	Type
Ok, 2 nuts missing	wheel Rims & Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

