

PLANT & EQUIPMENT

تقرير الفحص – 2007 رينو KERAX

الرقم التسلسلي: VF634DPA77D000807 | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١١٨٩

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
N/A	Add blue
Yes	Hill stand aid function
Yes	Horn off-on
N/A	Tachograph
N/A	Auto Lube
Ok	A/C
N/A	Navigation
Yes	ABS
N/A	Driver bed
Yes	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes	Retarder
N/A	Rear Axle Lifter
N/A	Radio
N/A	TRC
N/A	Camera sensor
Yes	Differential lock
Yes	Advanced emergency brake assist

Truck Cabin Details

Ok	Seat and Arm Support
Ok, driver door lock need service	Cab Doors & covers
Ok	Controls, Levers



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok
Ok, screen not visual sunburnt, air gauge not functional
Screen not visual sunburnt
Ok
Not cooling
Ok
Ok
Ok
N/A

Windows and Mirrors
Dashboard Screen, Gauges
Warning alarms message
Washer, Wipers
Air Conditioning & Heating System
Cab Floor Covering
Interior, Covers
Passenger Seat
Radio

Engine & Performance

Electronic
Renault DXI 11
Ok
Ok
Normal
Ok
Ok
Normal
Ok
Ok

Fuel Injection Type
Engine Model
Engine Cooling System
Engine Oil Check
Blowby
Exhaust System & Muffler
Belts & Air/Oil Filters
Smoke
Coolant
Fluid Leaks

Exterior Condition & Visual Inspection

Ok
Ok
Ok
Ok
Ok
Ok
Ok
Ok
Ok
Ok

Chassis, Frames
Sheet Metal, Covers
Steps, Grab Irons
Paintwork
Cooler Grill
Bumpers
Lights / Batteries
Fenders
Drum
Drum Pedestals



PLANT & EQUIPMENT

Ok	Drum Rollers
Ok	Drum Roller Ring
Ok	Flights
Ok	Chute Rotator
Ok	Water Tank
Ok	Exterior Mixer Controls

Power Train

Ok, minor leak at the right second differential	Axels/Differentials
Ok	Stabilizers, Beams
Ok	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Ok, manual	Transmission
Functional, need minor service	Clutch
N/A	Non-Driven Rear Drop Axle

hydraulics

Functional	PTO Pump
N/A	hydraulic cylinder
Ok	cabine lift cylinder & valve
Ok	Mixer cylinder
Ok	Mixer Drive Motor

Truck Limited Functional Test

Ok	Transmission Forward
Ok	Transmission Reverse
N/A	Automatic Group Select
Ok	Service Brake
Ok	Park Brake
Need minor service	Electrics
Ok	Retarder



PLANT & EQUIPMENT

Tires

R 90%, L 90%	(%) Axle 1 / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 2 Inside / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 2 Outside / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 3 Inside / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 3 Outside / RHS mm (%) / LHS mm
11.00 R20	Tire Size

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

