

PLANT & EQUIPMENT

تقرير الفحص – 2015 دووسان DL420A

الرقم التسلسلي: DWGCWLBBHF1010803 | الموقع: Dubai, الإمارات العربية المتحدة | رقم التعريف: ١١٧١

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
Not cooling	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
N/A	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
Yes	Horn Function

Operator Cabin Details

Need upholstery	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Front glass broken	Windows and Mirrors
Need service, not functional	Dashboard Screen, Gauges
Screen not functional	Warning alarms message
Not functional	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Need minor service	Cab Floor Covering
Ok	Cab Structure, Gard
Need minor service	Electrical System
Direct from fuel pump	Shut off

Engine & Performance

Mechanical	Fuel Injection Type
------------	---------------------



PLANT & EQUIPMENT

DE12TIA	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok, minor welding	Exhaust System & Muffler
Belt dry, filters needs change	Belts & Air/Oil Filters
Normal	Smoke
Normal water	Coolant
Minor leak from head gasket	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok	Engine Hood
Front right one step broken, rear left steps missing	Access Steps and Handrails
Ok, repainted	Exterior Paint Condition
Ok	Counterweight Condition
Ok	Wheel Fenders
Ok, need 4 bulbs	Lights Check
Need change	Battery Check
Ok	Covers

Power Train Inspection

Ok	Axles and Differentials
Minor oil leak	Transmission Gearbox
Ok	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- auto	Transfer Gear Type

Hydraulic System

OK, minor leak	Hydraulic Leaks
Ok, lift jacks minor leak	Lift and Tilt Hydraulic Jack
N/A	Steering Hydraulic Orbital



PLANT & EQUIPMENT

Ok
Minor leak from valve

Steering Hydraulic Jacks
Hydraulic Pumps and Valves

Limited Functional Testing & Operation

Ok Steering Function Test
Ok Transmission Operation Test
Ok Loader Stall Test
Ok Brake System Test
Ok Articulation Movement Check
Ok Loader Attachment Pins

Attachments

Bucket Width and Capacity

Ok Bucket Bottom Condition
Ok, one teeth broken Bucket Edge & Teeth Condition
Ok Bucket Side Condition
Ok Attachment Coupler

Tires Inspection

- Front Right
Deestone 26.5-25 Tire Brand & Size Details
50% Tire Remaining Life Percentage
Ok, tubless Tire Condition Notes
Ok Wheel Rims & Nuts
- Front Left
Hung-A 26.5-25 Tire Brand & Size Details
40% Tire Remaining Life Percentage
Ok, side cut, tubless Tire Condition Notes
Ok Wheel Rims & Nuts
- Rear Right
Hung-A 26.5-25 Tire Brand & Size Details
60% Tire Remaining Life Percentage
Ok, tubless Tire Condition Notes



PLANT & EQUIPMENT

Ok	Wheel Rims & Nuts
-	Rear Left
Loader plus 26.5-25	Tire Brand & Size Details
60%	Tire Remaining Life Percentage
Ok, tubless	Tire Condition Notes
Ok	Wheel Rims & Nuts

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

