

PLANT & EQUIPMENT

تقرير الفحص – 2016 دونجفينج LP10018RC

الرقم التسلسلي: LGAX2A130G1035307 | كم: ١٥٥٧٧ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١١٨٨

Key Features & Condition	
N/A	Safety Certification Label
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
Yes	(Emissions Status (Add blue
Yes	Hill stand aid function
Yes	Horn off-on
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Navigation
Yes	ABS
Yes	Driver bed
N/A	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes	Retarder
N/A	Rear Axle Lifter
Yes	Radio
N/A	TRC
N/A	Camera Sensor
N/A	Differential Lock
N/A	Advanced Emergency Brake Assist
Yes, Not functional	Hand Washing Pump
Yes , broken	Auto Greaser
Yes	Water Tank
N/A	Concrete Hose



PLANT & EQUIPMENT

Yes

Outrigger Cylinders

Yes

Nitrogen Bottle

Truck Cabin Details

Ok

Seat and Arm Support

Ok

Cab Doors & covers

Ok

Controls, Levers

Ok

Windows and Mirrors

Ok

Dashboard Screen, Gauges

urea sodium content is too low

Warning alarms message

Not functional

Washer, Wipers

Not functional

Air Conditioning & Heating System

Ok, minor cut

Cab Floor Covering

Ok

Interior, Covers

Ok

Passenger Seat

Ok

Radio

Truck Engine & Performance

Electronic

Fuel Injection Type

Ok

Engine Cooling System

Ok

Engine Oil Check

Normal

Blowby

Ok

Exhaust System & Muffler

Not checked; cabin lift control not functional

Belts & Air/Oil Filters

Normal

Smoke

Not checked; cabin lift control not functional

Coolant

Not checked; cabin lift control not functional

Fluid Leaks

Pump controls pannel

Ok

water pump

Ok

concrete mixer

Ok

PTO engine

Ok

Cooler gril

Ok

Remote control



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok

Panel control

Pump Engine & Performance

Electronic	Fuel Injection Type
DEUTZ BFGM1013	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok, the air filter housing is broken	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Ok	Fluid Leaks
Ok	Suspension Springs/Hangers
Ok, front bushes need replace	Suspension Bushings

Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
Ok	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Ok	Transmission
Ok	Clutch

Truck Limited Functional Test

Ok	Transmission Forward
Ok	Transmission Reverse
Ok, joint minor loose	Steering
N/A	Automatic Group Select
Ok	Service Brake
Ok	Park Brake



PLANT & EQUIPMENT

Ok, need minor service
Ok

Electrics
Retarder

Hydraulics

Ok	PTO Pump
Ok	hydraulic cylinder
Not functional	cabine lift cylinder & valve
Ok	Mixer cylinder
Not tested	Concrete pump
Ok	Outrigger Cylinders

Tires

R80%, L70%	(%) Axle 1 / RHS mm (%) / LHS mm
R80%, L80%	(%) Axle 2 Inside / RHS mm (%) / LHS mm
R80%, L80%	(%) Axle 2 Outside / RHS mm (%) / LHS mm
9.00 R20 Tube type	Tire Size

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م
دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة
هاتف: +97148861125
www.PlantAndEquipment.com