

تقرير الفحص – 2017 هيوفاي R210-7

الرقم التسلسلي: N601D02029 | ساعات: ٨٦٢٤ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٨٢

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok	Windows and Mirrors
OK/ hard visual sunburnt	Dashboard Screen, Gauges
Electrical alarm	Warning alarms message
Not functional	Washer, Wipers
Not functional	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure
Need minor service	Electrical System

Engine & Performance

Mechanical	Fuel Injection System
6BT- 5.9 - C	Engine Model
Ok, Broken coolant tank	Engine Cooling System



Ok	Engine Oil Check
Ok	Cooling System
Ok	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Minor leak from rocker gasket	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Need 3 bulbs	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok, swing drive minor leak	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Functional	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok	Boom Pins Condition
Functional	Excavator self- Drift Test
Ok	Arm Pins Condition



Minor	Hydraulic Pump Noise Check
Ok	Bucket Pins Condition
Minor loose	Swing Ring Bearing Movement Check
Functional	Swing Drive and Brake Test
Ok	Drive force Test

Attachments

Bucket	Attachments model
W1080mm, H1070mm, D980mm.	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

70%	Bushings
70%	Track shoes
L 70%, R 80%	Idlers
600	:Shoe width in mm
80	:Track pitch in mm
70%	Carrier rollers
70%	Track rollers
70%	Track links
70%	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

