

تقرير الفحص – 2018 ماسي فيرغسون MF7720

الرقم التسلسلي: VKKMX65EVJB108015 | ساعات: ٣٢٠٨ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ٩١٢

Key Features & Condition

N/A	Safety Certification Label
N/A	Environmental Protection Agency
N/A	A/C
Yes	PTO
Yes	4WED
N/A	All Wheel Steer
Yes	Point Linkage-3
Yes	Drawbar
N/A	Emission Compliance Label
N/A	Horn Function
Yes	Closed Cabin
Yes	CE Specification
Yes	Shift Speed Controller
Yes	Front Axle Suspension
Yes	Cabin Suspension
Yes	Engine Speed Memory Control
Yes	DEF
Yes	Spool valve
Yes	Crous control

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok, main control lever is broken	Controls, Levers
Ok, left side glass broken, front left mirror missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Service light is on	Warning alarms message



Ok, rear not functional
Not Functional
Ok
Ok
Need Service

Washer, Wipers
Air Condition & Heating System
Cab Floor Covering
Cab Structure
Electrical System

Engine & Performance

Electronic
AGCO POWER 200 Hp (147 Kw)
Ok
Ok
Normal
Ok
Need change
Normal
Ok
Ok

Fuel Injection Type
Engine Model
Engine Cooling System
Engine Oil Check
Blowby
Exhaust System & Muffler
Belts & Air/Oil Filters
Smoke
Coolant
Fluid Leaks

Exterior Condition & Visual Inspection

Ok
Ok
Ok
Ok
Ok
Ok, engine side sheets missing
Ok
Not Functional
Need change
Ok

Chassis
Engine Hood
Steering Linkage
Access Steps and Handrails
Exterior Paint Condition
Sheet Metal
Wheel Fenders
Lights Check
Battery Check
Rims, Wheel Nuts

Power Train Inspection

Ok
Ok
Ok

Axles and Differentials
Transmission Leak
Power Train force



Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- Auto 4 gear	Transfer Gear Type

Hydraulic System

Ok, minor	Hydraulic Leaks
Not tested	Remote Hydraulic Controls
Not tested	Steering Hydraulic Jacks
Not tested	Hydraulic Pumps and Valves
Not tested	(Cylinder(s)

Limited Functional Testing & Operation

Ok	Steering Function Test
Ok	Transmission Operation Test
Not tested	Cylinder Pins and Bushings
Ok	Braking System Test
Not tested	Spool Valve Electronic/ Manual

% Tires Estimated Remaining Life

-	Front Right
RUNGOD 18.4- 30	Tire Brand & Size Details
40%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
-	Front Left
BKT 18.4- 30	Tire Brand & Size Details
90%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
-	Rear Right
Galaxy 650/65R42	Tire Brand & Size Details
80%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
-	Rear Left
Galaxy 650/65R42	Tire Brand & Size Details
90%	Tire Remaining Life Percentage



يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

