

PLANT & EQUIPMENT

تقرير الفحص – 2023 اكس سي ام جي XCT80

الرقم التسلسلي: LXGCPA508PA003739 | كم: ٧٤٠٨ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١١٩٨

Key Features & Condition

N/A	CE Labeling
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Extended Fuel tank
N/A	Retarder
N/A	Rear Axle Lifter
Yes	Axle Steering 2

Truck Cab

Ok	Driver Seat
Ok	Switches, Levers
Gauges functional, screen is not functional	Gauges, Warn Lights
Not cooling	Aircon / Heater
Ok	Passenger Seat
Ok	Cab Doors
Ok, right small mirror cracked	Windows, Mirrors
Ok	Wipers, Washers
Ok	Interior, Covers
Ok	Radio

Crane operator cab

Ok	Driver Seat
Ok	Switches, Levers
Ok	Gauges, Warn Lights
N/A	Aircon / Heater



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok	Cab Doors
Ok	Windows
Ok	Wipers
Ok	Interior Covers

Engine

Electronic	Injection Type
wp12.375e50	Engine Model
Ok	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler
Ok	Cooling System
Normal	Smoke, Fume
Normal	Blow By
Ok	Belts, Pulleys
Ok, normal water	Coolant Condition

Visual inspection exterior

Ok, minor welding	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok, repainted	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Ok	Lights

Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
Wear-Out	Rubber Sleeves
Ok	Brake Pads/Disks
Functional	Compressor
Manual, need minor service	Transfer Gear
Ok	Universal Joints



PLANT & EQUIPMENT

Functional
Need service

Transmission
Clutch

Hydraulics / Steering

Ok

Hoses & Lines

Ok

Hydraulic Pump

Ok

PTO

Ok

Steering Cylinders

Ok

Steering Linkage

Carrier Limited Functional Test

Functional hard gear shift

Transmission Forward

Functional hard gear shift

Transmission Reverse

N/A

Automatic Group Select

Functional

Service Brake

Functional

Park Brake

Functional

Electrics

Not tested

Retarder

Crane Condition / Limited Test

Functional

Controls, Levers

Ok

Boom Conditions

Ok

Telescopic Segments

Ok

Hydraulic Cylinders

Functional

Swing Bearing / Drive

Ok

Hose Lines

Not functional

Lift Limitations

Ok

Hook

Functional

Outriggers

% Tires Condition

-

Right

60%

Axle 1

50%

Axle 2 Inside



PLANT & EQUIPMENT

70% (2019 Need change)	Axle 3 Outside
70% (2019 Need change)	Axle 3 Inside
60% (2019 Need change)	Axle 4 Outside
60% (2019 Need change)	Axle 4 Inside
-	Left
60%	Axle 1
50%	Axle 2 Inside
60% (2019 Need change)	Axle 3 Outside
60% (2019 Need change)	Axle 3 Inside
60% (2019 Need change)	Axle 4 Outside
40% (2019 Need change)	Axle 4 Inside

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

