

تقرير الفحص – 2012 دوosan DX340LC

ساعات: ٩٧٨١.٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٣٢٠٧٠٣

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple And Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System Addblue
N/A	Stabilizer Blade Condition
Yes	Horn

Operator Cabin Details

Ok	Seat And Arm Support
Ok	Cab Doors & Covers
Ok	Control Levers, Control Stick
Ok, no mirrors	Windows And Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning Alarms Message
Missing	Washer, Wipers
Not functional	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electronic	Fuel Injection System
Doosan DL08	Engine Model
Ok, need rust cleaning	Engine Cooling System



Ok	Engine Oil Check
Ok, normal water	Cooling System
Ok, end muffler need minor welding	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok, minor oil leak from head cover gasket	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps And Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok, some parts repainted	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Functional, little weak	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok, minor loose	Boom Pins Condition
Weak	Excavator Self- Drift Test
Ok	Arm Pins Condition



Ok, minor	Hydraulic Pump Noise Check
Ok, minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive And Brake Test
Ok	Drive Force Test

Attachments

Bucket	Attachments Model
W1060, H1200, D1000 mm	Size
Ok	Status
Ok	Coupler Status
N/A	Second Attachments Model
N/A	Size
N/A	Status

Undercarriage

50%	Bushings
60%	Track Shoes
60%	Idlers
600	:Shoe Width In Mm
80	:Track Pitch In Mm
50%	Carrier Rollers
40%	Track Rollers
60%	Track Links
60%	Sprocket Segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

