

Inspection report – 2012 Caterpillar 950H

Serial No: CAT0950HKJ5J01763 | Hours: 32005 | Location: Dubai, United Arab Emirates | SKU: 1020

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Yes
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok, fuel gauge need service
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Model	C7
Engine Cooling System	Ok
Engine Oil Check	Ok, gauge not original
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, filters need change
Smoke	Minor
Coolant	Normal water
Fluid Leaks	Minor Gasket leaks
Power	Little weak

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Counterweight Condition	Ok
Wheel Fenders	Ok
Lights Check	Ok
Battery Check	Need change
Covers	Ok

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Functional
Power Train force	Little weak
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi- auto

Hydraulic System

Hydraulic Leaks	OK, minor leaks
Lift and Tilt Hydraulic Jack	Ok, tilt minor leak
Steering Hydraulic Jacks	Ok, left minor leak

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pumps and Valves

Ok

Limited Functional Testing & Operation

Steering Function Test

Functional

Transmission Operation Test

Functional

Loader Stall Test

Ok

Brake System Test

Ok, park break need service

Articulation Movement Check

Ok, minor loose

Loader Attachment Pins

Ok, minor loose

Attachments

Bucket Width and Capacity

W2800, H1300, D950 mm

Bucket Bottom Condition

Minor welding

Bucket Edge & Teeth Condition

Ok, no teeth

Bucket Side Condition

Ok

Attachment Coupler

N/A

Tires Inspection

Front Right

-

Tire Brand & Size Details

Advance 23.5R25

Tire Remaining Life Percentage

70%

Tire Condition Notes

Good, Tubeless

Wheel Rims & Nuts

Ok

Front Left

-

Tire Brand & Size Details

Advance 23.5R25

Tire Remaining Life Percentage

80%

Tire Condition Notes

Good, Tubeless

Wheel Rims & Nuts

Ok

Rear Right

-

Tire Brand & Size Details

Advance 23.5R25

Tire Remaining Life Percentage

80%

Tire Condition Notes

Good, Tubeless

Wheel Rims & Nuts

Ok

Rear Left

-

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Brand & Size Details	Advance 23.5R25
Tire Remaining Life Percentage	80%
Tire Condition Notes	Good,Tubeless
Wheel Rims & Nuts	Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

