

Inspection report – 2013 Honda City

Serial No: MRHGM2648DP030948 | Km: 208226 | Location: Dubai, United Arab Emirates | SKU: 739

Specifications and Standards

4WD N ADraw Bar N ASpare Tire N\A Xenon Head Lights N\A Gear Shift Paddle Ok Rear Camera N\A Air Condition Ok Radio Ok 7 Seats N A

Interior

Seats Ok
Switches Ok
Gauges Ok
Aircon / Heater Ok
Ceiling Ok
Cab Doors Ok
Windows Ok

Wipers Ok, Motor sound

Floor Mates Ok

Engine

Model I-VTEC Leaks Ok
Oil Condition Ok
Exhaust Ok

Cooling System Ok\Coolant \Normal

Fuel Type Gasoline

Sound Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Blow By Ok\Normal

Belts Ok Power Ok

Size 1500cc\1.5L

Exterior

Chassis Lower left crossbar scratched

Under Engine Cover Missing
Door Handles Ok

Paintwork Ok, Two pieces repainted

Cooler Grill Ok
Bumpers Ok
Lights Ok

Power Train

Axels Ok
Gearbox Ok
Transmission Gear Ok
Transfer Gear Ok
Universal Joints Ok
Differentials Ok
Brake Drums/Disk Ok

Limited Functional Test

Drive Forward Ok
Drive Reverse Ok
Service Brake Ok
Steering Ok
Wheel Bearing Ok
Suspensions Ok
Park Brake Ok

Tires Axle 1

RHS mm (%) rem. 40% - 2023 \NEXEN

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com





LHS mm (%) 40% - 2023 \NEXEN

Cuts Ok Recapped Ok

Tires Axle 1

RHS mm (%) rem. 50% - 2022 \ROADMARCH LHS mm (%) 40% - 2021 \BRIDGESONE

Cuts Ok Recapped Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.



Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

