

Inspection report – 2014 Terex RT555

Serial No: 1T9T503CEW161848 | Location: Dubai, United Arab Emirates | SKU: 975

Key Features & Condition

CE Labeling	N/A
Automatic Shift	N/A
Semi-Automatic	YES
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Extended Fuel tank	N/A
Retarder	N/A
2 Axle Steering	YES

Truck Cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Ok, 2 gauges are not functional
Aircon / Heater	Not functional
Cab Doors	Ok
Windows, Mirrors	Ok
Wipers, Washers	Ok
Interior, Covers	Ok

Engine

Injection Type	Electrical
Engine Model	CUMMINS_ 6BTA 5.9
Leaks, Seals	Ok
Oil Condition	Ok
Exhaust/Muffler	Ok
Cooling System	Ok
SmOke, Fume	Normal
Blow By	Normal

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Belts, Pulleys	Ok
Coolant Condition	Normal water

Visual inspection exterior

Chassis, Frames	Ok
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok
Lights	Not functional
Batteries	Ok
Main Hook	Ok
Auxiliary Hook	Ok

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	N/A
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Semi-Automatic
Clutch	N/A

Hydraulics / Steering

Hoses & Lines	Ok, minor leaks
Hydraulic Pump	Ok
PTO	Ok
Steering Cylinders	Ok
Steering Linkage	Ok
Lift Limitations	Sensor not functional
Outriggers	Top pads minor cracks

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hook	Ok
Boom Cylinder	Minor rust, minor leak

Crane Condition / Limited Test

Drive Forward & Back	Ok
Controls, Levers	Ok
Boom Function	Ok
Telescopic Segments Function	Ok
Hydraulic Cylinders	Functional
Swing Bearing / Drive	Not tested due to a swing lock broken air hose
Hose Lines	Swing lock broken air hose (dry)
Lift Limitations	Sensot not functional
Main Hook Function	Ok
Auxiliary Hook Function	Ok
Outriggers Function	Ok
Park Brake	Ok

Tires Condition %

Right	-
Axle 1	30% DRY
Axle 2	60% Ok
Left	-
Axle 1	60% Ok
Axle 2	60% Ok
Size / Brand	ROADSTONE _ 26.5--25

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

