

Inspection report – 2016 Manitou 200ATJ

Serial No: 959602 | Location: Dubai, United Arab Emirates | SKU: 1038

Key Features & Condition

Safety Certification Label	N/A
Diesel Powered	Yes
Electric Operating System	Ok
Travel Alarm	Ok
Axle Based 4WD	Ok
Upper Control Station	Ok
Horn	Ok
extension Boom	Ok
Machine control panel	Ok

Engine

Model	kubota V2403-m-eu35
Injection	Mechanical
Oil Condition	Need change
Exhaust	Ok
Cooling System	Ok
Coolant	Normal water
Leaks	Ok
Sound	Ok
Blow By	Normal
Belts	Ok
Power	Ok

Exterior

Chassis	Ok
Sheet Metal	Ok, battery cover and engine side cover are missing,
Engine Hoods	Broken
Control Hood	Cracked

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Steps/Ladders	Ok
Boom Linkage	Ok
Paintwork	Ok
Cooler Grill	Ok
Frame Condition	Ok
Diesel Tank	Tank cover is missing
Lights	Ok
Platform Condition	Ok
Batteries	Ok

Hydraulics

Hoses, Lines, Swivel	Ok, minor leaks
Pump And Valve Bloc	Ok
Steering Cylinder	Ok
Platform angle cylinder	Ok
Articulating Boom Cylinders	Ok
Jib Cylinder	Ok
Platform Rotation Cylinder	Ok
Telescopic jack	Minor leak

Limited Functional Test

Drive Forward	Ok
Drive Reverse	Ok
Steering	Ok
carriage Function Controls	Need service
Boom Extension	Ok
360° Continuous turret rotation	Ok
Platform angle	Ok
Wheel Bearing	Ok
Platform control	Ok
brake system	OK
Lifting	Ok
Platform Rotation	Ok
Jib	Ok



Tires

Axle 1 right	20%
Axle 1 left	20%
Axle 2 right	20%
Axle 2 left	20%

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

