

PLANT & EQUIPMENT

Inspection report – 2016 TATA Daewoo M9AVF

Serial No: KL3M9AVF1GK000663 | Location: Dubai, United Arab Emirates | SKU: 1114

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	N/A
Hill stand aid function	Yes
Horn off-on	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Navigation	N/A
ABS	Yes
Driver bed	Yes
Moving off aid	N/A
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	N/A
Radio	N/A
TRC	N/A
Camera sensor	N/A
Differential lock	Yes
Advanced emergency brake assist	Yes
Water Tank	Yes

Truck Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Need service; rusty, hinges damaged

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates
Tel: +97148861125
www.PlantAndEquipment.com



PLANT & EQUIPMENT

Cab structure	Rear and front side dented
Controls, Levers	Need minor service
Windows and Mirrors	Front glass broken
Dashboard Screen, Gauges	Not functional
Warning alarms message	Not functional
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Need service
Interior, Covers	Need service
Passenger Seat	Need upholstery
Radio	N/A
Electrical System	Need service

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	DV15TIS
Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Blowby	Normal
Exhaust System & Muffler	Ok, welded
Belts & Air/Oil Filters	Ok, need change
Smoke	Normal
Coolant	Not checked, cabin lifting system need service
Fluid Leaks	Minor leaks
Starting	Start directly from the starter and off directly from the fuel pump

Exterior Condition & Visual Inspection

Chassis, Frames	Rusty
Frame Stamp Serial Number	Ok
Sheet Metal, Covers	Rusty, broken, dent
Steps, Grab Irons	Rusty and broken
Paintwork	Need repaint
Cooler Grill	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Bumpers	Need replace
Lights / Batteries	Front signal light missing , need 4 bulbs
Fenders	Missing
Suspension Springs/Hangers	Rusty, spring leafs minor loose
Suspension Bushings	Front and rear need replace
Water Tank	Ok, minor dent
Fuel tank	Ok, dent
Fuel tank protection	Rusty, broken
Air tank	Rusty
Air tank protection	Rusty, broken

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Need replace
Brake Pads/Disks	Need service
Compressor	Need service
Transfer Gear	Not functional
Universal Joints	Ok
Transmission	Not functional, manual
Clutch	Ok

Truck Limited Functional Test

Transmission Forward	Not functional
Transmission Reverse	Not functional
Steering	Ok
Automatic Group Select	N/A
Service Brake	Need service
Park Brake	Ok
Electrics	Need service
Retarder	Ok

hydraulics

PTO Pump	N/A
----------	-----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Water pump
cabine lift cylinder & valve

Not tested
Not functional, lift cylinder leaks

Tires

Axle 1 / RHS (%) / LHS (%)	L70%, R60%
Axle 2 / RHS (%) / LHS (%)	L60%, R50%
Axle 3 Inside / RHS (%) / LHS (%)	L50%, R60%
Axle 3 Outside / RHS (%) / LHS (%)	L60%, R50%
Axle 4 Inside / RHS (%) / LHS (%)	L70%, R60%
Axle 4 Outside / RHS (%) / LHS (%)	L40%, R60%
Tire Size	12 R22.5

Water Tank

size	5000 gallon
condition	Ok

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

