

## Inspection report – 2018 Mercedes Benz Actros 1845

Serial No: WDB96340310246651 | Location: Dubai, United Arab Emirates | SKU: 763

---

### Key Features & Condition

|                                 |     |
|---------------------------------|-----|
| Safety Certification Label      | Yes |
| Automatic Shift                 | Yes |
| Semi-Automatic                  | Yes |
| Cruise Control                  | Yes |
| Cabin Refrigerator              | N/A |
| Add Blue                        | Yes |
| Hill Stand Aid Function         | Yes |
| Horn Off-On                     | Yes |
| Tachograph                      | Yes |
| Auto Lube                       | N/A |
| A/C                             | Yes |
| Navigation                      | N/A |
| ABS                             | N/A |
| Driver Bed                      | Yes |
| Moving Off Aid                  | Yes |
| Lane Departure Warning System   | Yes |
| Extended Fuel Tank              | N/A |
| Retarder                        | Yes |
| Rear Axle Lifter                | Yes |
| Radio                           | Yes |
| TRC                             | N/A |
| Camera Sensor                   | N/A |
| Differential Lock               | Yes |
| Advanced Emergency Brake Assist | N/A |

---

### Truck Cabin Details

|                      |    |
|----------------------|----|
| Seat and Arm Support | Ok |
| Cab Doors & covers   | Ok |
| Controls, Levers     | Ok |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                                   |                                                                                                          |
|-----------------------------------|----------------------------------------------------------------------------------------------------------|
| Windows and Mirrors               | Ok                                                                                                       |
| Dashboard Screen, Gauges          | Ok                                                                                                       |
| Warning alarms message            | Ok, The transmission's/braking common lever is faulty, A malfunction in the exhaust gas treatment system |
| Washer, Wipers                    | Ok                                                                                                       |
| Air Conditioning & Heating System | Ok                                                                                                       |
| Cab Floor Covering                | Ok                                                                                                       |
| Interior, Covers                  | Ok                                                                                                       |
| Passenger Seat                    | Ok                                                                                                       |
| Radio                             | Ok                                                                                                       |

---

## Engine & Performance

|                          |                                                          |
|--------------------------|----------------------------------------------------------|
| Fuel Injection Type      | Electronic                                               |
| Engine Model             | M3B Eng. OM471, inline 6, 12.8 l, 330kW (449hp), 2200 Nm |
| Engine Cooling System    | Ok                                                       |
| Engine Oil Check         | Ok                                                       |
| Blowby                   | Normal                                                   |
| Exhaust System & Muffler | Ok                                                       |
| Belts & Air/Oil Filters  | Ok                                                       |
| Smoke                    | Normal                                                   |
| Coolant                  | Ok, normal water                                         |
| Fluid Leaks              | Ok                                                       |

---

## Exterior Condition & Visual Inspection

|                     |                      |
|---------------------|----------------------|
| Chassis, Frames     | Ok                   |
| Sheet Metal, Covers | Ok                   |
| Steps, Grab Irons   | Ok                   |
| Paintwork           | Ok                   |
| Cooler Grill        | Ok                   |
| Bumpers             | Ok, side minor crack |
| Lights / Batteries  | Ok                   |
| Fenders             | Ok                   |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Power Train

|                     |                                   |
|---------------------|-----------------------------------|
| Axels/Differentials | Ok                                |
| Stabilizers, Beams  | Ok                                |
| Rubber Sleeves      | Ok                                |
| Brake Pads/Disks    | Ok                                |
| Compressor          | Ok                                |
| Transfer Gear       | Ok, late response (alarm message) |
| Universal Joints    | Ok                                |
| Transmission        | Ok                                |
| Clutch              | N/A                               |

---

## Truck Limited Functional Test

|                        |    |
|------------------------|----|
| Transmission Forward   | Ok |
| Transmission Reverse   | Ok |
| Automatic Group Select | Ok |
| Service Brake          | Ok |
| Park Brake             | Ok |
| Electrics              | Ok |
| Retarder               | Ok |

---

## Tires

|                                          |                       |
|------------------------------------------|-----------------------|
| Axle 1 / RHS mm (%) / LHS mm (%)         | 70% / 70% Out of date |
| Axle 2 Inside / RHS mm (%) / LHS mm (%)  | 30% / 40% Out of date |
| Axle 2 Outside / RHS mm (%) / LHS mm (%) | 30% / 40% Out of date |
| Tire Size                                | 315 (80R22.5)         |

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

