

Inspection report – 2019 Kobelco SK220XDLC-10

Serial No: YQ15510120 | Hours: 7214 | Location: Dubai, United Arab Emirates | SKU: 1034

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	Yes
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Need upholstery
Cab Doors & covers	Lock need change
Control Levers, Control Stick	Ok
Windows and Mirrors	Right mirror missing, front glass broken
Dashboard Screen, Gauges	Ok
Warning alarms message	Limited engine power, failure hi speed
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	N/A
Cab Structure, Guard	Ok
Electrical System	Need minor service

Engine & Performance

Fuel Injection System	Mechanical
Engine Model	Hino EA-J05E-TA
Engine Cooling System	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Ok
Cooling System	Ok
Coolant	Normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Minor leak from oil sump gasket

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Track Frame minor dent & minor crack
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok, welded
Lights	Ok, 2 lights need bulb
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok, minor leak from Valve Block
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

Performance analysis

Boom Pins Condition	Ok
Excavator self- Drift Test	Ok
Arm Pins Condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok, minor loose
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Functional, right drive need service

Attachments

Attachments model	Bucket
Size	W 1200 - D 800 - H 1000
Status	Ok, with teeth
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

bushings	40%
Track shoes	90%
idlers	60%
shoe width in mm:	600
track pitch in mm:	80
carrier rollers	60%
Track rollers	40%
Track links	50%
Sprocket segments	70%

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

