

Inspection report – 2020 Caterpillar 216B3 with Sweeper

Serial No: CAT0216BCPWK03787 | Hours: 2642 | Location: Dubai, United Arab Emirates | SKU: 750

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Horn Function	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	N/A
Control Levers, Control Stick	Ok
Windows and Mirrors	N/A
Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	C2.2
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Smoke	Normal
Coolant	Ok, normal water
Leaks& seals	Minor oil leak from fuel pump gasket

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Protective Covers & Sheets	Ok
Engine Door	Ok
Lights	Ok, need 5 bulbs
Battery Check	Need change
Diesel Tank	Tank cover is missing
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Hydraulic Pumps and Valves	Ok

Limited Functional Testing & Operation

Steering Function Test	Ok
Skid steer Stall Test	Ok
Brake System Test	Ok
Attachment Pins	Ok
Final Drive Motors Test	Ok
Electrical System Check	Ok

Attachments

Attachments Model	Bucket
Size	W1550, H 750
Status	Ok
Coupler Status	Ok
Second Attachments Model	Boxbroom Sweeper (BS72)
Cleaning Widht	72"

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Working Flow	40-60 L/min
Working Pressure	16 Mpa
Status	New

Tires Estimated Remaining Life %

Front Right	70%
Front Left	70%
Rear Right	40%
Rear Left	40%
Size	10-16.5
Type	Tubeless
Wheel Rims & Nuts	3 missing nuts

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

