

Inspection report – 2022 Caterpillar 216B3 (UNUSED)

Serial No: CAT0216BAPWK05582 | Hours: 7 | Location: Dubai, United Arab Emirates | SKU: 774

Key Features & Condition

| | |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Operator's Manual | N/A |
| Equipment Parts Manual | N/A |
| Air Conditioning System | Yes |
| Emission Compliance Label | N/A |
| Attachment Coupler | N/A |
| Horn Function | Yes |
| Closed Cabin | Yes |

Operator Cabin Details

| | |
|-----------------------------------|----|
| Seat and Arm Support | Ok |
| Cab Doors & covers | Ok |
| Control Levers, Control Stick | Ok |
| Windows and Mirrors | Ok |
| Gauges | Ok |
| Warning alarms message | Ok |
| Washer, Wipers | Ok |
| Air Conditioning & Heating System | Ok |
| Cab Floor Covering | Ok |
| Cab Structure, Gard | Ok |
| Electrical System | Ok |

Engine & Performance

| | |
|--------------------------|------------|
| Fuel Injection Type | Mechanical |
| Engine Model | C2.2 |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Blowby | Normal |
| Exhaust System & Muffler | Ok |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|-------------------------|--------|
| Belts & Air/Oil Filters | Ok |
| Smoke | Normal |
| Coolant | Ok |
| Leaks& seals | Ok |

Exterior Condition & Visual Inspection

| | |
|----------------------------|----|
| Main Frame and Lift Arm | Ok |
| Protective Covers & Sheets | Ok |
| Engine Door | Ok |
| Lights | Ok |
| Battery Check | Ok |
| Exterior Paint Condition | Ok |

Hydraulic System

| | |
|------------------------------|----|
| Hydraulic Leaks | Ok |
| Lift and Tilt Hydraulic Jack | Ok |
| Steering Hydraulic Orbital | Ok |
| Hydraulic Pumps and Valves | Ok |

Limited Functional Testing & Operation

| | |
|-------------------------|----|
| Steering Function Test | Ok |
| Skid steer Stall Test | Ok |
| Brake System Test | Ok |
| Attachment Pins | Ok |
| Final Drive Motors Test | Ok |
| Electrical System Check | Ok |

Attachments

| | |
|--------------------------|------------------------------------|
| First Attachments model | Bucket |
| Size | W 1530, H700 , 0.36 m ³ |
| Status | Ok |
| Coupler status | Ok |
| Second Attachments model | N/A |
| Size | N/A |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Status N/A

Tires Estimated Remaining Life %

| | |
|-------------------|----------|
| Front Right | 100% |
| Front Left | 100% |
| Rear Right | 100% |
| Rear Left | 100% |
| Size | 10.16.5 |
| Type | Tubeless |
| Wheel Rims & Nuts | Ok |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

