

PLANT & EQUIPMENT

Inspection report – 2023 XCMG XCT80

Serial No: LXGCPA508PA003739 | Km: 7408 | Location: Dubai, United Arab Emirates | SKU: 1198

Key Features & Condition

CE Labeling	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Extended Fuel tank	N/A
Retarder	N/A
Rear Axle Lifter	N/A
2 Axle Steering	Yes

Truck Cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Gauges functional, screen is not functional
Aircon / Heater	Not cooling
Passenger Seat	Ok
Cab Doors	Ok
Windows, Mirrors	Ok, right small mirror cracked
Wipers, Washers	Ok
Interior, Covers	Ok
Radio	Ok

Crane operator cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Ok
Aircon / Heater	N/A
Cab Doors	Ok



PLANT & EQUIPMENT

Windows	Ok
Wipers	Ok
Interior Covers	Ok

Engine

Injection Type	Electronic
Engine Model	wp12.375e50
Leaks, Seals	Ok
Oil Condition	Ok
Exhaust/Muffler	Ok
Cooling System	Ok
Smoke, Fume	Normal
Blow By	Normal
Belts, Pulleys	Ok
Coolant Condition	Ok, normal water

Visual inspection exterior

Chassis, Frames	Ok, minor welding
Sheet Metal, Covers	Ok
Steps, Grab Irons	Ok
Paintwork	Ok, repainted
Cooler Grill	Ok
Bumpers	Ok
Lights	Ok

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Wear-Out
Brake Pads/Disks	Ok
Compressor	Functional
Transfer Gear	Manual, need minor service
Universal Joints	Ok
Transmission	Functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Clutch

Need service

Hydraulics / Steering

Hoses & Lines	Ok
Hydraulic Pump	Ok
PTO	Ok
Steering Cylinders	Ok
Steering Linkage	Ok

Carrier Limited Functional Test

Transmission Forward	Functional hard gear shift
Transmission Reverse	Functional hard gear shift
Automatic Group Select	N/A
Service Brake	Functional
Park Brake	Functional
Electrics	Functional
Retarder	Not tested

Crane Condition / Limited Test

Controls, Levers	Functional
Boom Conditions	Ok
Telescopic Segments	Ok
Hydraulic Cylinders	Ok
Swing Bearing / Drive	Functional
Hose Lines	Ok
Lift Limitations	Not functional
Hook	Ok
Outriggers	Functional

Tires Condition %

Right	-
Axle 1	60%
Axle 2 Inside	50%
Axle 3 Outside	70% (2019 Need change)

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Axle 3 Inside	70% (2019 Need change)
Axle 4 Outside	60% (2019 Need change)
Axle 4 Inside	60% (2019 Need change)
Left	-
Axle 1	60%
Axle 2 Inside	50%
Axle 3 Outside	60% (2019 Need change)
Axle 3 Inside	60% (2019 Need change)
Axle 4 Outside	60% (2019 Need change)
Axle 4 Inside	40% (2019 Need change)

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

