

Inspection report – 2025 JCB 3DX PLUS

Serial No: HAR3DXS5C03564163 | Hours: 17 | Location: Dubai, United Arab Emirates | SKU: 899

Key Features & Condition

|                                 |     |
|---------------------------------|-----|
| Safety Certification Label      | N/A |
| Environmental Protection Agency | N/A |
| A/C                             | N/A |
| Auxiliary Lines                 | Yes |
| 4WED                            | Yes |
| Extended Stick                  | N/A |
| Rear Quick Coupler              | N/A |
| All Wheel Steer                 | N/A |
| Fork                            | N/A |
| Emission Compliance Label       | Yes |
| Horn Function                   | Yes |
| Jack Hammer Line                | Yes |
| Radio                           | Yes |
| Tools                           | N/A |
| Operation Manual                | N/A |
| Greas Pump                      | N/A |

Operator Cabin Details

|                                |                |
|--------------------------------|----------------|
| Seat and Arm Support           | Ok             |
| Cab Doors & covers             | Ok             |
| Controls, Levers               | Ok             |
| Windows and Mirrors            | Ok, no mirrors |
| Dashboard Screen, Gauges       | Ok             |
| Warning alarms message         | Ok             |
| Washer, Wipers                 | Ok             |
| Air Condition & Heating System | Ok             |
| Cab Floor Covering             | Ok             |
| Cab Structure                  | Ok             |
| Electrical System              | Ok             |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Engine & Performance

|                          |                  |
|--------------------------|------------------|
| Fuel Injection Type      | Electronic       |
| Engine Model             | JCB 430 TAIN5-55 |
| Engine Cooling System    | Ok               |
| Engine Oil Check         | Ok               |
| Blowby                   | Normal           |
| Exhaust System & Muffler | Ok               |
| Belts & Air/Oil Filters  | Ok               |
| Smoke                    | Normal           |
| Coolant                  | Ok               |
| Fluid Leaks              | Ok               |
| Fuel Pump                | Ok               |

## Exterior Condition & Visual Inspection

|                            |    |
|----------------------------|----|
| Chassis                    | Ok |
| Engine Hood                | Ok |
| Access Steps and Handrails | Ok |
| Exterior Paint Condition   | Ok |
| Sheet Metal                | Ok |
| Wheel Fenders              | Ok |
| Lights Check               | Ok |
| Battery Check              | Ok |
| Boom                       | Ok |
| Stick                      | Ok |
| Stick Extension            | Ok |
| Rims, Wheel Nuts           | Ok |
| Loader Frame & Hinges      | Ok |

## Power Train Inspection

|                           |    |
|---------------------------|----|
| Axles and Differentials   | Ok |
| Transmission Leak         | Ok |
| Power Train force         | Ok |
| Transmission Noise Check  | Ok |
| Universal Joint Condition | Ok |

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Transfer Gear Type

Manual shift

---

## Hydraulic System

|                              |     |
|------------------------------|-----|
| Hydraulic Leaks              | Ok  |
| Lift and Tilt Hydraulic Jack | Ok  |
| Steering Hydraulic Jacks     | Ok  |
| Hydraulic Pumps and Valves   | Ok  |
| Swing Cylinders              | Ok  |
| Boom Cylinder                | Ok  |
| Stick Cylinder               | Ok  |
| Bucket Cylinder              | Ok  |
| Clamshell Cylinder           | N/A |

---

## Limited Functional Testing & Operation

|                             |    |
|-----------------------------|----|
| Steering Function Test      | Ok |
| Transmission Operation Test | Ok |
| Loader Stall Test           | Ok |
| Braking System Test         | Ok |
| Pins Boom                   | Ok |
| Pins Stick / Extension      | Ok |
| Rear Bucket Linkage         | Ok |
| Loader Pins & Hinges        | Ok |
| Outriggers & Pads           | Ok |
| Boom Side Tilt              | Ok |

---

## Attachments Estimated Remaining Life %

|                    |                      |
|--------------------|----------------------|
| Front Bucket       | -                    |
| Size               | H900, W2300, D550 mm |
| Condition          | Ok                   |
| Rear Bucket        | -                    |
| Size               | H700, W700, D450 mm  |
| Condition          | Ok                   |
| Attachment Coupler | Ok                   |

---

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Tires Estimated Remaining Life %

|                                |                           |
|--------------------------------|---------------------------|
| Front Right                    | -                         |
| Tire Brand & Size Details      | CEAT 12.5/80-18 Tube Type |
| Tire Remaining Life Percentage | 100%                      |
| Tire Condition Notes           | New                       |
| Front Left                     | -                         |
| Tire Brand & Size Details      | CEAT 12.5/80-18 Tube Type |
| Tire Remaining Life Percentage | 100%                      |
| Tire Condition Notes           | New                       |
| Rear Right                     | -                         |
| Tire Brand & Size Details      | CEAT 16.5-28 Tube Type    |
| Tire Remaining Life Percentage | 100%                      |
| Tire Condition Notes           | New                       |
| Rear Left                      | -                         |
| Tire Brand & Size Details      | CEAT 16.5-28 Tube Type    |
| Tire Remaining Life Percentage | 100%                      |
| Tire Condition Notes           | New                       |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

