

## Rapport d'inspection – 2002 Caterpillar M318

Numéro de série: 8AL00285 | Heure: 18268 | Lieu: United Arab Emirates | SKU: 794

---

### Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	Yes
Adjustable Boom System	Yes
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Back camera	N/A
Quick Coupler	N/A
Hydraulic Hammer Lines	Yes
Grapple and Shear Hydraulic Lines	Yes
Stabilizer Blade Condition	N/A
Horn	N/A
Schild Plate	Yes

### Operator Cabin Details

Seat and Arm Support	Ok, Need upholstery
Cab Doors & covers	Ok, Cover missing
Control Levers, Control Stick	Functional
Windows and Mirrors	Ok, Missing right mirror
Dashboard Screen, Gauges	Ok, need service
Warning alarms message	Ok, 1 indicator blinking
Washer, Wipers	Ok
Air Conditioning & Heating System	Functional, weak cooling
Cab Floor Covering	Need change
Cab Structure, Gard	Ok, no guard
Electrical System	Need minor service

### Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	3116T

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, normal water
Leaks& seals	Ok

---

## Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok, 3 covers are missing
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Not functional
Battery Check	Need change
Counterweight	Ok
Exterior Paint Condition	Ok,some parts are repainted

---

## Hydraulic System

Hydraulic Leaks	Minor
Boom Hydraulic Jack	Functional, 1 minor oil leaks
Hydraulic Pump & Valve Block	Functional
Mono Boom Jack	Functional
Bucket Hydraulic Jack	Functional
Arm Hydraulic Jack	Functional
Pump Noises Check	Normal
Bucket Swing cylinder	N/A
Schild Blade Jack	Ok, minor oil leak

---



## Transmission & drive train

Transmission Gear	Functional
Axles	Ok
Swivel Joint	Ok
Universal Joint	Ok

## Limited Functional Testing & Operation

Boom Pins Condition	Ok, minor loose
Excavator self- Drift Test	Functional
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Normal
Brack & Parking Brack	Functional
Suspension Lock	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Functional
Swing Drive and Brake Test	Functional, Break little weak
Drive force Test	Functional
Slewing Ring Lock	Ok

## Attachments

Attachments model	Bucket
Size	W520, H1100, D750 mm
Status	Ok
Coupler status	Ok
Second Attachments model	Schild blade
Size	W2500, H550 mm
Status	Ok

## Tires Estimated Remaining Life %

Front Right	30%
Front Left	20%
Rear Right	20%
Rear Left	20%
Size	10.00R20

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Type	Tube (on road)
Spacer Rings	N/A
Damages / Cuts	Minor

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

