

Rapport d'inspection – 2010 Komatsu D375A-5

Numéro de série: KMT00050J02019472 | Heure: 44648 | Lieu: Dubai, Émirats arabes unis | SKU: 1077

Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	Yes
Ripper Control Valve	Yes
Low Ground Pressure Tracks	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Ok, minor cut
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	SA6D170E-3
Engine Cooling System	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Normal water
Fluid Leaks	Ok, minor leak from first head cover gasket

Exterior Condition & Visual Inspection

Push Frame & Trunnions	Ok
Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Ok
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Ok
Push Arm Pivot Shaft	Ok
Tilt Linkage Pins & Bushings	Ok

Hydraulic System

Hydraulic Leaks	Minor
Ripper Lift Hydraulic Jacks	Ok
Ripper Angle Hydraulic Jacks	Ok
Tilt Hydraulic Jack	N/A
Angle Hydraulic Jack	Ok
Lift Hydraulic Jacks	Ok

Limited Functional Testing & Operation

Push Frame Pins	Ok
Blade Pins	Ok
Ripper Pins	Ok
Equalizer Bar Condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Bulldozer Stall Test	Ok
Steering Function Test	Ok
Blade Tilt and Lift Test	Ok
Undercarriage Pivot Pins	Ok
Transmission Test	Ok
Brake System Test	Ok
Torque Converter Test	Ok

Blade Inspection

Blade Base Condition	Ok
Spill Rack Condition	Ok
Blade Front Condition	Ok
Blade Edge Condition	Ok

Undercarriage Inspection

Right Side Undercarriage Wear	-
Undercarriage Bushings	20%
Undercarriage Shoes	60%
Front Idler Condition	50%
Rear Idler Condition	N/A
Carrier Roller Condition	50%
Track Links Condition	50%
Sprocket Condition	30%
Roller Condition	20%
Track Canon Condition	Ok
Left Side Undercarriage Wear	-
Undercarriage Bushings	20%
Undercarriage Shoes	60%
Front Idler Condition	50%
Rear Idler Condition	N/A
Carrier Roller Condition	50%
Track Links Condition	50%
Sprocket Condition	60%
Roller Condition	10%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Track Canon Condition

Ok

Track Width Measurement

W610, H320 mm

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

