

## Rapport d'inspection – 2013 Volvo L105

Numéro de série: VCE0L105C00001073 | Heure: 15275 | Lieu: Dubai, Émirats arabes unis | SKU: 977

---

### Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	N/A

---

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok, left mirror broken
Dashboard Screen, Gauges	Ok
Warning alarms message	Park break failure/ reduced shift function
Washer, Wipers	Ok
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok, not original
Cab Structure, Gard	Ok
Electrical System	Ok

---

### Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Model	Volvo D7D
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

---

## Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok, repainted
Counterweight Condition	Ok
Wheel Fenders	Ok
Lights Check	2- Ok, 4 not functional
Battery Check	Ok

---

## Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok
Power Train force	weak du to park break
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi- auto

---

## Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Loader Stall Test	Ok
Brake System Test	Ok
Articulation Movement Check	Ok
Loader Attachment Pins	Ok

---

## Attachments

Bucket Width and Capacity	W1350, h1250, d950 mm
Bucket Bottom Condition	Ok
Bucket Edge & Teeth Condition	Ok
Bucket Side Condition	Ok
Attachment Coupler	Ok

---

## Tires Inspection

Front Right	-
Tire Brand & Size Details	China 23.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New, tube type
Wheel Rims & Nuts	Ok
Front Left	-
Tire Brand & Size Details	China 23.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New, tube type
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	Green 23.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New, tube type
Wheel Rims & Nuts	Ok
Rear Left	-
Tire Brand & Size Details	Gann shan 23.5-25
Tire Remaining Life Percentage	100%

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Tire Condition Notes

New, tube type

Wheel Rims & Nuts

Ok

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

