

## Rapport d'inspection – 2015 Caterpillar 966H

Numéro de série: CAT0966HCBJ601214 | Heure: 34889 | Lieu: Dubai, Émirats arabes unis | SKU: 916

---

### Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Yes
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	N/A

---

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok, cover is missing
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Screen low visibility (sunburnt)
Warning alarms message	Screen low visibility (sunburnt)
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Need minor service

---

### Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Model	Cat C11
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, mixed with water
Fluid Leaks	Ok

---

## Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok, rear left lader need minor welding
Exterior Paint Condition	Ok
Counterweight Condition	Ok
Wheel Fenders	Ok
Lights Check	Ok, need 2 bulbs
Battery Check	Ok

---

## Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi-auto

---

## Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok,3th gear not functional
Loader Stall Test	Ok
Brake System Test	Ok, parking brake need service
Articulation Movement Check	Ok
Loader Attachment Pins	Ok, tilt pin minor loose
Electrical System Check	Ok
Supplemental Steering Test	Ok

## Attachments

Bucket Width and Capacity	W3100,H1500, D1150 mm
Bucket Bottom Condition	Ok, minor crack
Bucket Edge & Teeth Condition	Minor dent , no teeth
Bucket Side Condition	Ok, no side cutter
Attachment Coupler	Ok

## Tires Inspection

Front Right	-
Tire Brand & Size Details	TRIANGLE 26.5R25
Tire Remaining Life Percentage	40%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok
Front Left	-
Tire Brand & Size Details	TRIANGLE 26.5R25
Tire Remaining Life Percentage	40%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	TRIANGLE 26.5R25
Tire Remaining Life Percentage	40%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok
Rear Left	-

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



# PLANT & EQUIPMENT | AUCTIONS

Tire Brand & Size Details	TRIANGLE 26.5R25
Tire Remaining Life Percentage	40%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

