

Rapport d'inspection – 2015 Tadano GR-600EX

Numéro de série: 6009126 | Heure: 27731 | Lieu: Dubai, Émirats arabes unis | SKU: 1014

Key Features & Condition

CE Labeling	N/A
Automatic Shift	Yes
Semi-Automatic	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Extended Fuel tank	N/A
Retarder	Yes
2 Axle Steering	Yes

Truck Cab

Driver Seat	Ok, need seat cover
Switches, Levers	Ok
Gauges, Warn Lights	Screen need service (sunburnt)
Aircon / Heater	N/A
Cab Doors	Ok
Windows, Mirrors	Ok
Wipers, Washers	Ok
Interior, Covers	Ok

Engine

Injection Type	Mechanical
Engine Model	mitsubishi 8m80-tl
Leaks, Seals	Ok
Oil Condition	Ok
Exhaust/Muffler	Ok
Cooling System	Ok
Smoke, Fume	Normal
Blow By	Normal

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Belts, Pulleys	Ok
Coolant Condition	Ok

Visual inspection exterior

Chassis, Frames	Ok
Sheet Metal, Covers	Ok, minor rust
Steps, Grab Irons	Ok
Paintwork	Ok
Cooler Grill	Ok
Bumpers	Ok
Lights	Not functional
Batteries	Need replace
Main Hook	Ok
Auxiliary Hook	N/A

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Automatic
Clutch	N/A

Hydraulics / Steering

Hoses & Lines	Ok
Hydraulic Pump	Ok
PTO	Ok
Steering Cylinders	Ok
Steering Linkage	Ok
Lift Limitations	Ok
Outriggers	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Crane Condition / Limited Test

Drive Forward & Back	Ok
Controls, Levers	Ok
Boom Conditions	Ok
Telescopic Segments	Ok
Hydraulic Cylinders	Ok
Swing Bearing / Drive	Ok
Hose Lines	Ok
Lift Limitations	Ok
Main Hook	Ok
Auxiliary Hook	N/A
Outriggers	Ok

Tires Condition %

Right	-
Axle 1	60%
Axle 2	60%
Left	-
Axle 1	60%
Axle 2	80%
Size / Brand	29.5-25 Bridgestone

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

