

PLANT & EQUIPMENT

Rapport d'inspection – 2016 Dongfeng LP10018RC

Numéro de série: LGAX2A130G1035307 | Km: 15577 | Lieu: Dubai, Émirats arabes unis | SKU: 1188

Key Features & Condition

Safety Certification Label	N/A
Automatic Shift	N/A
Semi-Automatic	N/A
Cruise Control	N/A
Cabin Refrigerator	N/A
Emissions Status (Add blue)	Yes
Hill stand aid function	Yes
Horn off-on	Yes
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Navigation	N/A
ABS	Yes
Driver bed	Yes
Moving off aid	N/A
Lane departure warning system	N/A
Extended Fuel tank	N/A
Retarder	Yes
Rear Axle Lifter	N/A
Radio	Yes
TRC	N/A
Camera Sensor	N/A
Differential Lock	N/A
Advanced Emergency Brake Assist	N/A
Hand Washing Pump	Yes, Not functional
Auto Greaser	Yes , broken
Water Tank	Yes
Concrete Hose	N/A
Outrigger Cylinders	Yes

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Nitrogen Bottle	Yes
-----------------	-----

Truck Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	urea sodium content is too low
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not functional
Cab Floor Covering	Ok, minor cut
Interior, Covers	Ok
Passenger Seat	Ok
Radio	Ok

Truck Engine & Performance

Fuel Injection Type	Electronic
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Not checked; cabin lift control not functional
Smoke	Normal
Coolant	Not checked; cabin lift control not functional
Fluid Leaks	Not checked; cabin lift control not functional

Pump controls pannel

water pump	Ok
concrete mixer	Ok
PTO engine	Ok
Cooler gril	Ok
Remote control	Ok
Panel control	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Pump Engine & Performance

Fuel Injection Type	Electronic
Engine Model	DEUTZ BFGM1013
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, the air filter housing is broken
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok
Suspension Springs/Hangers	Ok
Suspension Bushings	Ok, front bushes need replace

Power Train

Axels/Differentials	Ok
Stabilizers, Beams	Ok
Rubber Sleeves	Ok
Brake Pads/Disks	Ok
Compressor	Ok
Transfer Gear	Ok
Universal Joints	Ok
Transmission	Ok
Clutch	Ok

Truck Limited Functional Test

Transmission Forward	Ok
Transmission Reverse	Ok
Steering	Ok, joint minor loose
Automatic Group Select	N/A
Service Brake	Ok
Park Brake	Ok
Electrics	Ok, need minor service
Retarder	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Hydraulics

PTO Pump	Ok
hydraulic cylinder	Ok
cabine lift cylinder & valve	Not functional
Mixer cylinder	Ok
Concrete pump	Not tested
Outrigger Cylinders	Ok

Tires

Axle 1 / RHS mm (%) / LHS mm (%)	R80%, L70%
Axle 2 Inside / RHS mm (%) / LHS mm (%)	R80%, L80%
Axle 2 Outside / RHS mm (%) / LHS mm (%)	R80%, L80%
Tire Size	9.00 R20 Tube type

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

