

## Rapport d'inspection – 2016 JCB 3DX

Numéro de série: HAR3DXSUL01495014 | Heure: 2802 | Lieu: United Arab Emirates | SKU: 806

---

### Key Features & Condition

|                                 |     |
|---------------------------------|-----|
| Safety Certification Label      | N/A |
| Environmental Protection Agency | N/A |
| A/C                             | N/A |
| Auxiliary Lines                 | N/A |
| 4WED                            | Yes |
| Extended Stick                  | N/A |
| Rear Quick Coupler              | N/A |
| All Wheel Steer                 | N/A |
| Fork                            | N/A |
| Emission Compliance Label       | N/A |
| Horn Function                   | N/A |

### Operator Cabin Details

|                                |                                |
|--------------------------------|--------------------------------|
| Seat and Arm Support           | Ok                             |
| Cab Doors & covers             | Ok                             |
| Controls, Levers               | Ok                             |
| Windows and Mirrors            | N/A                            |
| Dashboard Screen, Gauges       | Ok, Speed gauge not functional |
| Warning alarms message         | Ok                             |
| Washer, Wipers                 | Not functional                 |
| Air Condition & Heating System | N/A                            |
| Cab Floor Covering             | Ok, Minor cut                  |
| Cab Structure                  | Ok                             |
| Electrical System              | Ok                             |

### Engine & Performance

|                       |            |
|-----------------------|------------|
| Fuel Injection Type   | Mechanical |
| Engine Model          | JCB 444    |
| Engine Cooling System | Ok         |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |                  |
|--------------------------|------------------|
| Engine Oil Check         | Oil need change  |
| Blowby                   | Normal           |
| Exhaust System & Muffler | Ok               |
| Belts & Air/Oil Filters  | Ok               |
| Smoke                    | Normal           |
| Coolant                  | Ok, Normal water |
| Fluid Leaks              | Ok               |

---

## Exterior Condition & Visual Inspection

|                            |                    |
|----------------------------|--------------------|
| Chassis                    | Ok                 |
| Engine Hood                | Ok                 |
| Access Steps and Handrails | Ok                 |
| Exterior Paint Condition   | Ok, Repainted      |
| Sheet Metal                | Ok                 |
| Wheel Fenders              | Ok                 |
| Lights Check               | Ok                 |
| Battery Check              | Ok                 |
| Boom                       | Ok                 |
| Stick                      | Ok                 |
| Stick Extension            | N/A                |
| Rims, Wheel Nuts           | Ok, 1 nuts missing |
| Loader Frame & Hinges      | Ok                 |

---

## Power Train Inspection

|                           |        |
|---------------------------|--------|
| Axles and Differentials   | Ok     |
| Transmission Leak         | Ok     |
| Power Train force         | Ok     |
| Transmission Noise Check  | Ok     |
| Universal Joint Condition | Ok     |
| Transfer Gear Type        | Manual |

---

## Hydraulic System

|                              |    |
|------------------------------|----|
| Hydraulic Leaks              | Ok |
| Lift and Tilt Hydraulic Jack | Ok |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                            |    |
|----------------------------|----|
| Steering Hydraulic Jacks   | Ok |
| Hydraulic Pumps and Valves | Ok |
| Swing Cylinders            | Ok |
| Boom Cylinder              | Ok |
| Stick Cylinder             | Ok |
| Bucket Cylinder            | Ok |
| Clamshell Cylinder         | Ok |

---

## Limited Functional Testing & Operation

|                             |                                |
|-----------------------------|--------------------------------|
| Steering Function Test      | Ok                             |
| Transmission Operation Test | Ok                             |
| Loader Stall Test           | Ok                             |
| Braking System Test         | Ok, Park break need maintenace |
| Pins Boom                   | Ok, Minor loose                |
| Pins Stick / Extension      | Ok, Minor loose                |
| Rear Bucket Linkage         | Ok                             |
| Loader Pins & Hinges        | Ok, Minor loose                |
| Outriggers & Pads           | Ok                             |
| Boom Side Tilt              | Ok                             |

---

## Attachments Estimated Remaining Life %

|                    |                       |
|--------------------|-----------------------|
| Front Bucket       | -                     |
| Size               | W2150, H1000, D500 mm |
| Condition          | Ok                    |
| Rear Bucket        | -                     |
| Size               | W760, H720, D500 mm   |
| Condition          | Ok                    |
| Attachment Coupler | Ok                    |

---

## Tires Estimated Remaining Life %

|                                |                 |
|--------------------------------|-----------------|
| Front Right                    | -               |
| Tire Brand & Size Details      | CEAT 15.5/80-18 |
| Tire Remaining Life Percentage | 80%             |
| Tire Condition Notes           | Ok              |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                                |                |
|--------------------------------|----------------|
| Front Left                     | -              |
| Tire Brand & Size Details      | MRF 15.5/80-18 |
| Tire Remaining Life Percentage | 60%            |
| Tire Condition Notes           | Ok             |
| Rear Right                     | -              |
| Tire Brand & Size Details      | JCB 16.9-28    |
| Tire Remaining Life Percentage | 70%            |
| Tire Condition Notes           | Not Original   |
| Rear Left                      | -              |
| Tire Brand & Size Details      | JCB 16.9-28    |
| Tire Remaining Life Percentage | 70%            |
| Tire Condition Notes           | Not Original   |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

