

Rapport d'inspection – 2018 Caterpillar 336D2

Numéro de série: CAT0336DHFAJ12344 | Heure: 7136 | Lieu: United Arab Emirates | SKU: 792

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	Yes
Grapple And Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System Addblue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A

Operator Cabin Details

Seat And Arm Support	Ok
Cab Doors & Covers	Ok
Control Levers, Control Stick	Ok

Windows And Mirrors Ok, Right Mirror Is Missing

Dashboard Screen, Gauges

Warning Alarms Message

Ok
Washer, Wipers

Ok
Air Conditioning & Heating System

Ok
Cab Floor Covering

Ok
Cab Structure, Gard

Ok
Electrical System

Ok
Ok

Engine & Performance

Fuel Injection System Electronic
Engine Model C9 Engine

Engine Cooling System Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Engine Oil Check Ok
Cooling System Ok

Coolant Ok, Normal Water

Exhaust System & Muffler Ok
Belts & Air/Oil Filters Ok

Smoke Check Normal Blowby Normal

Leaks & Seals Ok

Exterior Condition & Visual Inspection

Main Frame & Track Frame Ok
Protective Covers & Sheets Ok
Engine Hood Ok

Side Access Doors Ok, Minor Dents
Steps And Handrails Ok, Minor Dents

Boom Condition Ok
Bumpers & Catwalk Condition Ok
Arm Condition Ok
Lights Ok
Battery Check Ok
Cabin Compartments Ok
Exterior Paint Condition Ok

Hydraulic System

Hydraulic Leaks Ok

Boom Hydraulic Jack Ok, Minor Oil Leak

Hydraulic Pump & Valve Block Ok

Bucket Hydraulic Jack Ok, Minor Oil Leak

Arm Hydraulic Jack Ok

Performance Analysis

Boom Pins Condition Ok
Excavator Self- Drift Test Ok
Arm Pins Condition Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com





Hydraulic Pump Noise Check Ok

Bucket Pins Condition Ok. Minor Loose

Slewing Ring Bearing Movement Check Ok
Swing Drive And Brake Test Ok
Drive Force Test Ok

Attachments

Attachments Model Bucket

Size W1340 H1300 D1000 Mm

Status Ok
Coupler Status Ok
Second Attachments Model N/A
Size N/A
Status N/A

Undercarriage

Bushings 60% Track Shoes 80% 60% Idlers Shoe Width In Mm: 600 Mm Track Pitch In Mm: 140 Mm **Carrier Rollers** 70% Track Rollers 60% Track Links 60% **Sprocket Segments** 60%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

