

PLANT & EQUIPMENT

Rapport d'inspection – 2019 Bobcat S450

Numéro de série: AUVB14511 | Heure: 5562 | Lieu: Dubai, Émirats arabes unis | SKU: 1175

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	Yes
Equipment Parts Manual	N/A
Air Conditioning System	Ok, not cooling
Emission Compliance Label	N/A
Closed Cabin	Yes
Horn Function	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Door lock need allignment
Control Levers, Control Stick	Ok, one stick missing one button
Windows and Mirrors	Ok
Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok, not cooling
Cab Floor Covering	Ok, need minor service
Cab Structure, Guard	Ok
Electrical System	Ok
Start key	Ok
Main Safty Switch	Ok

Engine & Performance

Fuel Injection Type	Electrical
Engine Model	JDICL0 1.8LEA
Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Blowby	Normal

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Exhaust System & Muffler	Normal
Belts & Air/Oil Filters	Ok
Smoke	Ok
Coolant	Coolant
Leaks& seals	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Protective Covers & Sheets	Ok
Engine Door	Ok
Lights	Need 4 bulbs
Battery Check	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital (drive motor)	Ok
Hydraulic Pumps and Valves	Need to change filter

Limited Functional Testing & Operation

Drive Function Test	Functional
Skid steer Stall Test	Functional
Brake System Test	Functional
Attachment Pins	Functional
Final Drive Motors Test	Functional
Park Break	Functional

Attachments

Attachments model	Bucket
Size	W 1800, D 800, H500
Bottom condition	Ok
Edge & teeth condition	Ok, no teeth
Bucket side condition	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Coupler status

Ok

Tires Estimated Remaining Life %

Front Right	40% cut on the side
Front Left	70%
Rear Right	70%
Rear Left	70%
Size	10-16.5
Type	Tube less
Wheel Rims & Nuts	Ok, rims minor bent all 4

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

