

Rapport d'inspection – 1996 CMI PR500C

Lieu: Dubai, Émirats arabes unis | SKU: 1269463

Key Features & Condition

Safety Certification Label N/A **Equipment Parts Manual** N/A Horn Function Yes Travel Alarm N/A Operator's Manual N/A **Emission Compliance Label** N/A **Emergency switch** Yes Water Spray System Yes Water Tank Yes

Operator Cabin Details

Seat and Arm Support N/A

control levers, Control swithes Functional

Dashboard Screen, Gauges Most are not functional

Warning alarms message N/A

Electrical System Need minor service

Floor cover mat N/A

Engine & Performance

Fuel Injection System Type Mechanical

Fluid Leaks Ok
Engine Oil Check Ok
Exhaust System and Muffler Ok

Exhaust Smoke Normal

Engine Model Details caterpillar 2408

Engine Cooling System Ok, clamp is leaking

Engine Blow-by Check Normal
Belts and Air/Oil Filters Ok

Coolant Normal water

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com





Exterior Condition & Visual Inspection

Ok Chassis, Frame Ok **Rotor Compartment Doors** Engine Hood, door Ok Stairs, Handrails Ok Collecting Conveyor Ok Ok Paint condition Ok **Cutting Bits** Rotor Mandrel Ok Sheet Metal Ok Conveyor Frame Ok Conveyor Rollers Ok Ok Lights **Batteries** Ok

Hydraulic System

Hoses & Lines Ok

Pump And Valve Bloc Functional
Steering Cylinders Functional
Rotator Door Pin Cylinders Functional

Cutter Cylinder Functional, 1 minor oil leak
Collecting Conveyer Cylinders Functional, minor oil leak

Collecting Conveyer Hight Cylinders Functional
Rotator Door Cylinders Functional
Machine Rear Lift cylinder Functional
Machine Front Lift cylinders Functional

Limited Functional Testing & Operation

Drive forward Functional
Drive revers Functional
Steering Functional
Conveyor test Functional

Station controls Most are functional

Rotor Mandrel Functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com





Rotor Door Functional
Engine speed control Functional
Water spray system Not functional

U/C - Estimated Remaining Life mm (%)

bushings	60%
shoes	70%
idlers	60%
carrier rollers	60%
track links	60%
sprockets	70%
track pitch mm	45 mm
shoe width mm	355 mm

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.



Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

