

## Rapport d'inspection – 2018 Caterpillar 336D2

Heure: 7136.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1402011

---

### Key Features & Condition

|                                     |     |
|-------------------------------------|-----|
| Safety Certification Label          | N/A |
| Boom Hydraulic Check Valve          | N/A |
| Adjustable Boom System              | N/A |
| Automatic Lubrication System        | N/A |
| Arm Hydraulic Check Valve           | N/A |
| Diesel Particulate Filter           | N/A |
| Hydraulic Hammer Lines              | Yes |
| Grapple And Shear Hydraulic Lines   | N/A |
| Diesel Exhaust Fluid System Addblue | N/A |
| Stabilizer Blade Condition          | N/A |
| Horn                                | N/A |

### Operator Cabin Details

|                                   |                             |
|-----------------------------------|-----------------------------|
| Seat And Arm Support              | Ok                          |
| Cab Doors & Covers                | Ok                          |
| Control Levers, Control Stick     | Ok                          |
| Windows And Mirrors               | Ok, Right Mirror Is Missing |
| Dashboard Screen, Gauges          | Ok                          |
| Warning Alarms Message            | Ok                          |
| Washer, Wipers                    | Ok                          |
| Air Conditioning & Heating System | Ok                          |
| Cab Floor Covering                | Ok                          |
| Cab Structure, Gard               | Ok                          |
| Electrical System                 | Ok                          |

### Engine & Performance

|                       |            |
|-----------------------|------------|
| Fuel Injection System | Electronic |
| Engine Model          | C9 Engine  |
| Engine Cooling System | Ok         |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |                  |
|--------------------------|------------------|
| Engine Oil Check         | Ok               |
| Cooling System           | Ok               |
| Coolant                  | Ok, Normal Water |
| Exhaust System & Muffler | Ok               |
| Belts & Air/Oil Filters  | Ok               |
| Smoke Check              | Normal           |
| Blowby                   | Normal           |
| Leaks & Seals            | Ok               |

---

## Exterior Condition & Visual Inspection

|                             |                 |
|-----------------------------|-----------------|
| Main Frame & Track Frame    | Ok              |
| Protective Covers & Sheets  | Ok              |
| Engine Hood                 | Ok              |
| Side Access Doors           | Ok, Minor Dents |
| Steps And Handrails         | Ok, Minor Dents |
| Boom Condition              | Ok              |
| Bumpers & Catwalk Condition | Ok              |
| Arm Condition               | Ok              |
| Lights                      | Ok              |
| Battery Check               | Ok              |
| Cabin Compartments          | Ok              |
| Exterior Paint Condition    | Ok              |

---

## Hydraulic System

|                              |                    |
|------------------------------|--------------------|
| Hydraulic Leaks              | Ok                 |
| Boom Hydraulic Jack          | Ok, Minor Oil Leak |
| Hydraulic Pump & Valve Block | Ok                 |
| Bucket Hydraulic Jack        | Ok, Minor Oil Leak |
| Arm Hydraulic Jack           | Ok                 |

---

## Performance Analysis

|                            |    |
|----------------------------|----|
| Boom Pins Condition        | Ok |
| Excavator Self- Drift Test | Ok |
| Arm Pins Condition         | Ok |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                                     |                 |
|-------------------------------------|-----------------|
| Hydraulic Pump Noise Check          | Ok              |
| Bucket Pins Condition               | Ok. Minor Loose |
| Slewing Ring Bearing Movement Check | Ok              |
| Swing Drive And Brake Test          | Ok              |
| Drive Force Test                    | Ok              |

---

## Attachments

|                          |                      |
|--------------------------|----------------------|
| Attachments Model        | Bucket               |
| Size                     | W1340 H1300 D1000 Mm |
| Status                   | Ok                   |
| Coupler Status           | Ok                   |
| Second Attachments Model | N/A                  |
| Size                     | N/A                  |
| Status                   | N/A                  |

---

## Undercarriage

|                    |        |
|--------------------|--------|
| Bushings           | 60%    |
| Track Shoes        | 80%    |
| Idlers             | 60%    |
| Shoe Width In Mm:  | 600 Mm |
| Track Pitch In Mm: | 140 Mm |
| Carrier Rollers    | 70%    |
| Track Rollers      | 60%    |
| Track Links        | 60%    |
| Sprocket Segments  | 60%    |

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

