

Rapport d'inspection – 2013 Caterpillar M318D

Heure: 16335.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1402034

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	Yes
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	Yes
Back camera	Yes
Quick Coupler	N/A
Hydraulic Hammer Lines	Yes
Grapple and Shear Hydraulic Lines	N/A
Mono Boom	Yes
Stabilizer Blade Condition	Yes
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	No control switch
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok, no Gard
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	C6.6

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Leaks& seals	Minor oil pan Gasket leak

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Ok, 1 bulb need change
Battery Check	Ok
Counterweight	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Mono Boom Jack	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok
Pump Noises Check	Ok
Bucket Swing cylinder	Ok

Transmission & drive train

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Transmission Gear	Ok
Axles	Ok
Swivel Joint	Ok
Universal Joint	Ok

Limited Functional Testing & Operation

Boom Pins Condition	Ok
Excavator self- Drift Test	Ok
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Brack & Parking Brack	Ok
Suspension Lock	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok
Slewing Ring Lock	Ok

Attachments

Attachments model	digging bucket
Size	W820, H1100, D800 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

Tires Estimated Remaining Life %

Front Right	70%
Front Left	70%
Rear Right	70%
Rear Left	70%
Size	10.00-20
Type	Twin / Mono

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Spacer Rings

No

Damages / Cuts

No

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

