

Rapport d'inspection – 2018 Caterpillar D8R

Heure: 31514.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1413245

Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	Yes
Ripper Control Valve	Yes
Low Ground Pressure Tracks	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A
Radio	Yes
Horn	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok, fuel level sensor voltage above normal \96-3 service
Washer, Wipers	Ok, two wipers need service
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok, has some cuts
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	C15

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, Normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Push Frame & Trunnions	Ok
Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Ok
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Ok
Push Arm Pivot Shaft	Ok, left minor oil leak
Tilt Linkage Pins & Bushings	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift Hydraulic Jacks	Ok
Ripper Lift Hydraulic Jacks	Ok, minor oil leak
Tilt Hydraulic Jack	Ok
Angle Hydraulic Jack	N/A
Ripper Angle Hydraulic Jacks	Ok

Limited Functional Testing & Operation

Push Frame Pins	Ok, minor Loose
Blade Pins	Ok, minor Loose
Ripper Pins	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Equalizer Bar Condition	Ok
Bulldozer Stall Test	Ok
Steering Function Test	Ok
Blade Tilt and Lift Test	Ok
Undercarriage Pivot Pins	Ok, minor Loose
Transmission Test	Ok
Brake System Test	Ok
Torque Converter Test	Ok
Electric system check	Ok, need minor service

Blade Inspection

Blade Base Condition	Ok, minor welding
Spill Rack Condition	Ok
Blade Front Condition	Ok, minor welding
Blade Edge Condition	Ok

Undercarriage Inspection

Right Side Undercarriage Condition	-
Undercarriage Bushings	60%
Undercarriage Shoes	70%
Front Idler Condition	70%
Rear Idler Condition	70%
Carrier Roller Condition	N/A
Track Links Condition	70%
Sprocket Condition	60%
Roller Condition	70%
Track Canon Condition	60%
Left Side Undercarriage Condition	-
Undercarriage Bushings	60%
Undercarriage Shoes	70%
Front Idler Condition	70%
Rear Idler Condition	70%
Carrier Roller Condition	N/A
Track Links Condition	70%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Sprocket Condition	70%
Roller Condition	60%, two pics 40%
Track Canon Condition	70%
Track Width Measurement	W600 / L250 /Grouser height 60 mm

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

